		rr	<b>_</b>	NEW MEXICO OIL CONSERVATION COMMISSION						
I C R L	F A	н О	Q U							
S A	С	υ	A			2.10.05	Nilos	160 District	тт	
P C	I L	R S	R T	Name B: W. Weaver		• .		<u>169</u> District		
D I C F T I	IT	.	E R	Time of Departure	)0 am Time	of Return	3:00 più	Car No.		
IĈA	Y		н	T- the space below indi	rate the purpose	of the trip a	and the du	ties		
N T		1	o U	In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.						
O N			R	Signature $\underline{B} \omega$	Weave					
				1 Well B-8-7-26 H.E.	Dringo Topkin	HIPRAC	alled off	-		
P O	0	7		because of rain.	·	π1. Γ α Π Ο.				
	Plugged 3-20-85. Plugging was not witnessed. According to information received from the operator this well was plugged in the same manner as the Tonkin #2 which was									
	P & A'd and witnessed $3-22-85$ .									
				· · ·						
							•			
				•		·				
								•		
							· ·			
								•		
								Post ID-2		
								11-1-85 P+A		
· ·								/ • //		
				·						
						•				
				Mileage	Per Die	2m	Hour	5		
				UIC	UIC		UIC.			
				RFA						
				.Other <u>16</u>	9 Other		Othe	r7		
	-									
TYPE INSPECTION			л. ИC	INSPE CLASSIFI				ATURE OF SPECIFIC DR FACILITY INSPEC		
11 - P - C - T - R - W -	<ul> <li>House</li> <li>Plugg</li> <li>Plugg</li> <li>Plugg</li> <li>Repain</li> <li>Water</li> <li>Mater</li> <li>Water</li> <li>Other</li> </ul>	ekeep ying Test Trst ar/Wo rflow ap or r Con	Cleanu rkover Spill	U = Underground Injec related to injec resulting from 1 injection and pr tests, surface i R = Inspections rela tion O = Other - Inspecti Reclamation Fund	ction Control - Any tion project, facil njection into any wi oduction wells, wat njection equipment, ting to Roclamation ons not related to	ity, or Vell or ell. (SWD, 2nd er flows or pre plugging, etc. Fund Activity injection or Th	P Iry I issure C ) S U U N G 7	<ul> <li>Drilling</li> <li>Production</li> <li>Injection</li> <li>Combined prod. operations</li> <li>SWD</li> <li>Underground Std</li> <li>General Operat</li> <li>Facility or log</li> <li>Modeling</li> </ul>	orage ion	
				Reclamation Fund E = indicates some f	orm of enforcement	action taken in	the H		_	

field (show immediately below the letter U, R or O)