## WELL INFORMATION AND PLUGGING PROCEDURE

OPERATOR a. D. Raby on James 7. Raby WELL NAME Keys #1 LOCATION LOCATION un D mc. 33 township 6 range 26 FOOTAGE 330 FWL 990FNL COUNTY Chaves, N.M.

Invitation to Bid No.

termination.

The information herein is taken from OCD well files. The bidder is responsible for obtaining all available data including a review of such files, on-site inspection and any other sources.

Failure to review available information will not justify for implementing supplemental rates or contract modification or

SUMMARY	WELL DATA

41/2 @ 955

SURFACE CASING: 8 5/8 0100

**INTERMEDIATE CASING:** 

PRODUCTION CASING:

TUBING:

**OTHER INFORMATION:** 

PLUGGING PROCEDURE including site preparation and cleanup Spot 35 st of comment across perfs + pull out of hole with the. ι, Cut 1/2 cog e 480' + pull. 2. Run in hole with they + tag plug moide of cog stub. Fill hole with mont to make 3. hole with coment to senface. 4. dry hole marsen, clean + level becation .