

RECEIVED BY  
JAN 24 1985  
O.C.D. Approved.  
Budget Bureau No. 42-R1424  
ARTESIA, OFFICE

Form 9-331  
Dec. 1973

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR

Sun Exploration & Production Co. ✓

3. ADDRESS OF OPERATOR

P. O. Box 1861 Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2310' FNL & 2310' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(other)		

5. LEASE NM 022584	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Sun Federal	
9. WELL NO. 5	
10. FIELD OR WILDCAT NAME N/A	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-7 <del>S</del> R-26-E	
12. COUNTY OR PARISH Chaves	13. STATE NM
14. API NO. 30-005-10426	
15. ELEVATIONS (SHOW DF, KDB, AND WD)	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged in August 1981.  
MIRU Dig out well head (pump 20 sxs cmt in rat hole, filled w/sand)  
Cut off wellhead, pull 2 loose jts 4 1/2 casg. Ran 2 3/8 tbg open ended to 1044.  
Spot 25 sxs cmt 1044-720. Raise tbg to 720. Spot 25 sxs 720-397. Raise tbg to 220, spot 30 sxs cmt 220 to surface. POH w/2 3/8 tbg. Install well head marker.

*James H. P. P. P.*

*Post TD-3  
11-9-84  
E.P. G.*

*Post TD-2  
11-6-84  
PWT*

Subsurface Safety Valve, Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE Associate Account. DATE 9-7-84

APPROVED BY (Off. Sgd.) PETER W. CHESTER TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
(This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY:  
JAN 27 1985