

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TWO COPIES*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R14245. LEASE DESIGNATION AND SERIAL NO.
NM-0443819

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
FEDERAL9. WELL NO.
110. FIELD AND POOL, OR WILDCAT
Wildcat11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 25, T6S-R29E12. COUNTY OR PARISH
Chaves13. STATE
N. Mex.1. OIL WELL ☐ GAS WELL ☐ OTHER DRY2. NAME OF OPERATOR
SOUTHWEST PRODUCTION CORPORATION3. ADDRESS OF OPERATOR
P. O. Box 936, Roswell, New Mexico 882014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FS&EL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4166 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-28-66 Drilled to TD 8165' in granite wash; no productive zones were encountered. Drill stem tests of porous intervals at 2915-3075', 3075-3200' & 6900-7122' recovered only small amounts of drilling fluid; tests at 7860-7902' and 7991-8085' recovered 1500' and 1600' respectively of drilling fluid and salt water.

Your approval is requested to plug and abandon by setting 50 sx cement plugs through drill pipe across the following intervals: 7800-7950', 7400-7450', 6600-6750', 5650-5750', 3400-3500', 3000-3100' and 1750-1825'. A 10 sx plug will be set in the top of the surface pipe; 8-5/8" casing is set at 1812' with 600 sx, cement circulated to surface.

Approval for this procedure was given by telephone to W. Clements, Jr.

RECEIVED

OCT 29 1968

O. E. C.
ARTESIA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

C. R. Appledorn

TITLE

Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

OCT 22 1968

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.