

COMPANY		PROPERTY NAME	WELL NO.
DATE	LOCATION (ULSTR)	FOOTAGE	
API NO.		POOL	

Top phase in 9 5/8 csg @ 10861 CIBP
 Spot 100' @ 7861
 Spot 100' @ 4861
 Spot 100' @ 3944
 Per 9 5/8 @ 2910 + squeeze. Leave 100'
 plug inside + outside of csg. Tag
 Perforate 9 5/8 + 13 3/8 @ 350' + squeeze
 Bring cement to surface, close in
 csg valves on 13 3/8 + 20" as they
 circulate.
 Leave 9 5/8 csg full.
 Perforating gun will need to be
 decentralized to perforate 9 5/8 + 13 3/8 csg

CASING RECORD:

