

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DATE SUBMITTED | |
| DATE RECEIVED | |
| U.S.G.S. | |
| FIELD OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION
 Orig&2cc: OCC, *W.A. Gressett*
 cc: Regional Office
 cc: Partners
 cc: file

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. |

| | |
|---|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Sinclair Oil & Gas Company / | 8. Farm or Lease Name J.G. O'Brien |
| 3. Address of Operator P.O. Box 1920, Hobbs, New Mexico | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>9S</u> RANGE <u>29E</u> NMPM. | 10. Field and Pool, or Wildcat Wildcat |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County Chaves |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3500' TD - total depth drilled - PBTD 3451'. Perforated 4-1/2" OD casing 3114-17' and 3123-27'.
 8-5/8" OD 20# casing set @ 302' and cemented w/200 sacks.
 4-1/2" OD 9.5# casing set @ 3500' and cemented w/400 sacks. Top of cement behind casing @ 2290'.
 Dry Hole.

PROPOSE TO: Plug and Abandon as follows:
 Spot 50 sks. cement from 2850-3350' and across perms. 3114-3127'. Fill hole w/heavy mud.
 Cut 4-1/2" OD casing @ approx. 2173' and pull. Spot 25 sacks cement plug in top of 4-1/2" OD casing stub 2123-2223'. Spot 50 sacks cement plug 600-700'. Spot 50 sacks cement plug bottom of 8-5/8" OD casing 250-350'. Spot 10 sacks cement plug in top of 8-5/8" OD surface casing, install regulation marker for dry hole. Clean and level location.

(confirming verbal between W.A. Gressett, NMOCC & D.N. Williams, Sinclair)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *W.A. Gressett* TITLE Superintendent DATE 3-27-67

APPROVED BY *W.A. Gressett* TITLE 3RD AND 4TH DEPT. SUPERVISOR DATE MAR 29 1967

CONDITIONS OF APPROVAL, IF ANY: