

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN PLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R142.
5. LEASE DESIGNATION AND SERIAL NO.

N. M. 064442

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Hanson Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 1515, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 990' FSL & FEL
Sec. 26, T-14-S, R-27-E, NMPM
Chaves County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3450' GL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Miller Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Undesignated

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 26-14S-27E

12. COUNTY OR PARISH
Chaves

13. STATE
N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒ setting whipstock

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1- 3-70 P.B.T.D. 5515' with 125 sx. Class C + 3# NaCl per sx. + 15 lbs. sand per sx.
- 1- 4-70 Reaming @ 5694'. Dress cmt. & drill of whipstock.
- 1- 5-70 Drlg. and reaming rat hole @ 5704'.
- 1- 6-70 Drlg. 5886' lime. Dev. 2° @ 5790' & 2° @ 5815'.
- 1- 7-70 Drlg. 6036' lime & chert. Dev. 1-1/2° @ 5965' & 1-1/4° @ 6020'.
- 1- 8-70 Drlg. 6360' lime & chert. Dev. 1° @ 6160'.
- 1- 9-70 Drlg. 6640' lime & chert. Dev. 3/4° @ 6409' & 3/4° @ 6584'.
- 1-10-70 Drlg. 6816' lime & chert. Dev. 3/4° @ 6640' & 1° @ 6775'.
- 1-11-70 Drlg. 7072' lime & shale. Dev. 1° @ 7050'.
- 1-12-70 Drlg. 7249' lime, shale & sand. Dev. 1° @ 7211'.

RECEIVED

FEB 16 1970

O. C. C.

18. I hereby certify that the foregoing is true and correct

SIGNED *Larry F. Schwan*

TITLE Exec. Vice President

DATE 1-12-70

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD
FEB 13 1970
Date
ACTING District Engineer

*See Instructions on Reverse Side