16.

## SUBMIT UNITED STATES DEPARIMENT OF THE INTERIOR (Other inverse side)

RIPLICATE\*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

| NM 06442     |
|--------------|
| I INTO UUTTA |

| 1  | AM-C   | , O | 442   | -  |    |       |    |
|----|--------|-----|-------|----|----|-------|----|
| IF | INDIAN | , A | LLOTT | EB | OB | TRIBE | MA |

| GEOLOGICAL SURVEY   |  | 6. IF INDIAN, ALLOTTER OR TRIBE NAME  |
|---|--|---|
| SUNDRY NOTICE (Do not use this form for proposal Use "APPLICAT  | ES AND REPORTS ON WELLS s to drill or to deepen or plug back to a different reservoir. ION FOR PERMIT—" for such proposals.) | NMC64442-E  |
| OIL GAS WELL OTHER  2. NAME OF OPERATOR Hanson Oil Corpor   |  | 7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME  Miller Federal   |
| 3. ADDRESS OF OPERATOR  P. O. BOX 1515, I  4. LOCATION OF WELL (Report location cle See also space 17 below.) At surface 990' FSL & | Roswell, New Mexico 88201  arly and in accordance with any State Coulement E D  990' FEL                                     | 9. WELL NO.  1  10. FIELD AND POOL, OR WILDCAT  Undesignated  11. SEC., T., R., W., OR BLE. AND BURYET OR AREA. |
| Sec. 26, T-1<br>Chaves Count  | L4-S, R-27-E, N.M.P. 6 1972  Ty, New Mexico  15. ELEVATIONS (Show whether DF, RT, OR, etc. C. 3450 G.L.  ARTESIA, OFFICE     | Sec. 26, T-14-S,R-2<br>E.   |

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:                             |   | SUBSEQUENT REPORT OF: |  |   |
|---|---|-----------------------|--|---|
| TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE | PULL OR ALTER CASING<br>MULTIPLE COMPLETE<br>ABANDON® |                       | SHOOTING OR ACIDIZING ABANDONMENT  | X |
| REPAIR WELL   | CHANGE PLANS  |                       | (Norz: Report results of multiple completion on Well<br>Completion or Recompletion Report and Log form.) |   |
| (Other)   |   |                       | Completion or Recompletion Report and Log form.)   |   |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

The captioned well was plugged and abandoned in the following manner per verbal instructions of Mr. Knauf received on July 13, 1972:

8-2-'72 25 sx. plug 8290-7175'

8-3-'72 Cut and recovered 6501' of 3-1/2 in. tubing.

Cut and recovered 6476' of 5-1/2 in. casing. 8-4-172

35 sx. plug 6528-6428'

35 sx. plug 5025-4925'

35 sx. plug 2900-2800'

35 sx. plug 1670-1570'

8-5-'72 20 sx. plug 100'-surface.

The intervals between plugs was filled with 10# mud.

A regulation dry hole marker was set, and the location has been cleaned and is ready for inspection. 7.4

| 18. I hereby certify that the foresoing is true and correct  SIGNED WARD C. WANNIAM TITLE Geologist | DATH 8-25-172 |
|---|---------------|
| (This mare for Federal or State office use)  OP PROVED BY   | DATE          |
| A BOWNAIN SER   |               |

\*See Instructions on Reverse Side