

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	005 30-015-60114
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	White
8. Well No.	1
9. Pool name or Wildcat	Race Track (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3794' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Klabzuba Operating Company	8. Well No. 1
3. Address of Operator 930 West First Street, Ft. Worth, TX 76102	9. Pool name or Wildcat Race Track (Devonian)	
4. Well Location Unit Letter I : 700 Feet From The East Line and 2500 Feet From The South Line Section 13 Township 10S Range 27E NMPM Chaves County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3794' KB		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Temporary Abandonment <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up Wedge Wireline, Set CIBP @ 6554'. Run in hole w/ tubing and hang unanchored @ 4740. Rig up Western. Load hole and pressure up to 500 psi. Held for 30 minutes. Rig down Western & Tatum Well Service. Shut well in. Hole loaded w/ 9.3 ppg produced water. Pressure Test witnessed by Gary Williams.

Requesting approval to temporarily abandon for 5 years.

This Report of Operations
Submitted by

5/98

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John M. Roberts TITLE Petroleum Engineer DATE 3/31/93
TYPE OR PRINT NAME John M. Roberts TELEPHONE NO. (817) 336-5757

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 4/14/93
CONDITIONS OF APPROVAL, IF ANY: