

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

CIS
AP

Form C-103
Revised March 25, 1999

WELL API NO.

30-005-60144

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VO-5081

7. Lease Name or Unit Agreement Name:

South Acme AZM State

7. Well No.

#1

8. Pool name or Wildcat

Undes. Foor Ranch Pre-Permian

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter **M4** : **660** feet from the **South** line and **660** feet from the **West** line

Section **30** Township **8S** Range **27E** NMPM **Chaves** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3997' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: set and cement production casing ☒

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/28/02 - MIRU rotary tools.

3/30/02 - Tagged cement plug at 1275' and drilled out. Tagged formation at 2200'. Drilling new formation at 5:00 PM. Notified Phil Hawkins with NMOCD of resume drilling.

4/13/02 - Reached TD of 7-7/8" hole at 6675' at 1:45 AM. Run logs and sidewall cores. Loggers TD 6669'.

4/14/02 - Ran 158 joints (6676.97') casing set at 6675' as follows:

49 joints 5-1/2" 15.5# SB (2021.69')

109 joints 5-1/2" 15.5# MV (4655.28')

Float shoe set at 6675'. Float collar set at 6633.09'. Bottom marker set at 5647.43'. Top marker set at 4653.31'. Cemented with 550 sxs Pecos Valley Lite + 1 pps D44 + 4 pps D42 + .2% D65 + .3% D167 + .2% D46 + .2% D13 (yld 1.42, wt 13).

4/14/02 - PD at 2:15 AM. Bumped plug to 1670 psi, held OK.

Notified Van Barton with NMOCD of operations.

Rig released at 6:00AM 4/15/02.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE April 16, 2002

Type or print name Susan Herpin

Telephone No. 505-748-1471

(This space for State)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY

Conditions of approval, if any:

APR 24 2002