

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

DEC 28 1970

O.C.C.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Drilling Well</b>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator <b>TWINLAKES OIL COMPANY</b>	5. State Oil & Gas Lease No.
3. Address of Operator <b>P. O. Box 1582, Roswell, N. M. 88201</b>	7. Unit Agreement Name
4. Location of Well UNIT LETTER <b>D</b> , <b>460</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>12</b> TOWNSHIP <b>9 S.</b> RANGE <b>28 E.</b> NMPM.	8. Farm or Lease Name <b>O'Brien "D"</b>
	9. Well No. <b>1</b>
	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3945' KB</b>	12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <b>Plug back</b> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7615'. Set 3 plugs of 50 scks of Class C Cement each at depths of 7200-7300, 6400-6500, and 2650-2750.

Plan to attempt completion in San Andres formation in open hole section from 2590 - 2650. Will clean out to 2650, run tubing with formation packer to be set at 2590, acidize, and swab to test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. H. Freeman* TITLE Pres. DATE Dec. 26, 1970

APPROVED BY *W. A. Gressett* TITLE OIL AND GAS INSPECTOR DATE DEC 28 1970

CONDITIONS OF APPROVAL, IF ANY: