			NW OIL	CONS. COMMISSION	168		
0.771	U ED STATES	SUBMIT IN TR	RIPLIPATE	DD Form approved.	6/51		
orm 9-331 May 1963)	DEPARTMENT OF THE INTERIOR			- NN 8827 BUDGET BUREAU No.	42-R1424		
((ay 1903)	GEOLOGICAL SURVEY	verse side)		5. LEASE DESIGNATION AND NM-7814	SERIAL NO.		
	SUNDRY NOTICES AND REPORTS ON	WELLS		6. IF INDIAN, ALLOTTEE OR	TRIBE NAME		
(Do not use this	form for proposals to drill	or to deepen d	or plug back	to SLUP-23			
	ervoir. Use "APPLICATION FOR I	PERMIT-" TOP S	RECEIV	ED 7. UNIT AGREEMENT NAME			
OIL GAS WELL WELL	OTHER Salt Water Dispos	al Well		_			
++	Officer Odd Find to Find		CED 1 7 1	00 8. FARM OR LEASE NAME			
. NAME OF OPERATOR Read & Stevens, Inc.			SEP I ()	Federal "L"			
ADDRESS OF OPERATOR			O. C. D	9. WELL NO.			
P.O. Box 1518, Roswell,	NM 88201		ARTESIA OF	1	UDCAT		
	location clearly and in acco	ordance with S	tate	Haystack Willy	Shil		
requirements.* See also space 17 below.)					11. SEC. T.,R.,M.,OR BLK. AND		
At surface 1980: FEL & 660: FNL Sec. 21, T-6-S, R-27-E, N.M.P.M.				SURVEY OR AREA			
1900 122 4 000	,			Sec. 21-6S-27E, N.M.			
4. PERMIT NO.	15. ELEVATIONS (Show 4073' GR, 408		T,GR,etc.)	12. COUNTY OR PARISH 13. Chaves Ne	STATE W Mexico		
6. Chec	ck Appropriate Box To Indicate	Nature of No	tice, Report	, Other Data			
NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
STATE OF CHIT OFF	T PULL OR ALTER CASING		WATER SHUT-OF	FF REPAIRING WE	LL T		
TEST WATER SHUT-OFF FRACTURE TREAT	MULTIPLE COMPLETE	 	FRACTURE TREA	1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	ING		
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR	ACIDIZING X ABANDONMENT*	<u> </u>		
REPAIR WELL	CHANGE PLANS		(Other)_		_		
(Other)				t results of multiple complet			
				or Recompletion Report and L			
17.DESCRIBE PROPOSED OR CO	OMPLETED OPERATIONS (Clearly Stains any proposed work. If we	II is directio	onally drille	, and give pertinent dates, i d give subsurface locations a	nd measured		
and true vertical depth	hs for all markers and zones	pertinent to t	this work.)*				
0.10.02	dizo w/1000gal 15 % HCL avo c	ate 2 1/2 BPM	@ 1000psi. I	SIP 500psi, 5min 300psi, 10mi	n 250psi		
8-19-82 Acidize w/1000gal 15% HCL, avg rate 2 1/2 BPM @ 1000psi. ISIP 500psi, 5min 300psi, 10min 2 30 min 200psi. Acidized w/3000gal 20% HCL avg rate 4 BPM, @ max pres 2400psi 4.9 BPM. ISIP 30min- 20" vacuum.							
		τ					
- Andrew SEP は 1982 利用							
		€. ₋	.d 1. 1	ان مان المان ا المان المان ا			
				GAS BRAIRINET			
I hereby certify that th	ne foregoing is true and corre	ect		EW MEXICO			
SIGNED 6	- Two the	TLE Drilling	& Production	n Manager DATE 9-2-83	2		
(This space for Federa	al or State office use)			DATE			
APPROVED BY		ITLE		DATE			
CONDITIONS OF APPROVAL	., IF ANY:			ACCEPTED FOR RECORD)		
				Promise I am I did I am I			
	*See Instr	ructions on Re	everse Side				
				SEP 151982			
				all			
				U.S. GEOLOGICAL SURV	cY		
				ROSWELL, NEW MEXICO			