<u>August 26, 1971</u>

Tripped out of hole. Ran 7-7/8 bit, bottom hole reamer, 13 5-7/8 DC's, and DP and drilled from 2891 to 3181. TOTCO at 2963' 4½°. Bit #3 J-8 in hole, has 18½ rotating hrs on it. Mud wt. 9.5 Vis. 38

August 27, 1971

Drlg. 3547'. 366' in 20 rotating hrs. Bit #3 out at 3236', made 155'.

4140 at 3236'
5140 at 3316'
Mud wt. 9.3 Vis. 37
3 hrs. trip time

<u>August 28, 1971</u>

Trip at 3681. Lime, 134' in  $6\frac{1}{4}$  hrs. Bit #5. Bit #4 445' in 17 hrs. Mud wt. 9.4 Vis. 35  $6^{\circ}$  @ 3507'.

<u>August 29, 1971</u>

Single shot Sperry Sun Survey 6° inclination N88°W. Pulled drill pipe, inserted monel drill collar, ran to bottom, ran multi shot on horizontal displacement, 85.74' at N 74° 5" west, pulled drill pipe, ran 7-7/8 Smith bit 5" dyna drill, 2½° bent sub, 7- 6½" DC's and DP to 3681. mud 9.3 Vis.38

August 30, 1971

Oriented tool w/single shot, first picture tool facing S 5° E, turned DP and tool 90° to right; second picture, tool S 85° W, started drilling w/dyna drill at 9 AM. Drlg. to 3744'. Ran single shot 6½° south 70° west, pulled dyna drill, ran 7-7/8" bit, monel collar, 17 DC's, drlg. to 3807', ran single shot, 8½° south 46° west, drilled to 3880' 9° south 40° west. Now drilling @ 3940', preparing to run single shot. Mud wt. 9.3 Vis. 36°

August 31, 1971

TD 3945' Mud wt. 9.3 Vis. 36
Ran single shot survey 3920'. 94 S 40 Trip out of hole w/Bit #7. 7-7/8 Smith Bit, dyna drill, 2120 bent sub, 1 monel DC, 7 steel collars to 3920'. Ran single shot. 1st picture facing N 20 W, tool turned 90° to left. 2nd picture tool facing S 50 W, turned; tool 250 L 3rd picture tool facing S 25 W. Start drilling w/dyna drill. Drilled to 3945 Shaft on Dyna Drill broke, leaving rotating sub, 5" OD X 12" long, bit sub 5½" X 6" long and bit. Now running sho catch, over shot, jars, to catch fish. Mud 132.36, Water 39.87