

RECEIVED NEW MEXICO OIL CONSERVATION COMMISSION

AUG 31 1972

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

O. C. C.

ARTESIAN OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator JACK F. GRIMM		5. State Oil & Gas Lease No.
3. Address of Operator P. O. BOX 35 ABILENE, TEXAS 79604		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>N</u> <u>880</u> FEET FROM THE <u>South</u> LINE AND <u>1,500</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>11S</u> RANGE <u>29E</u> NMPM.		8. Farm or Lease Name J. P. White, Jr.
15. Elevation (Show whether DF, RT, GR, etc.) 3751.5 GR		9. Well No. 1
		10. Field and Pool, or Wildcat Und.
		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1102.

Request permission to cut and pull 8 5/8" intermediate string and set 40 sx cement plug @ 8 5/8" cut-off stub, 40 sx @ 250', and 10 sx in top of surface.

Verbal permission given this date to Mr. Grimm from Mr. W. A. Gressett by telephone.

Spotted 40 sx plug @ 1,123'

Spotted 40 sx plug @ 250

Spotted 40 sx plug @ top hole plug

Set Dry Hole Marker

6. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack F. Grimm TITLE Operator DATE August 25, 1972

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 13 1973

DATE OF APPROVAL, IF ANY: