

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN 1
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0390086

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NA

7. UNIT AGREEMENT NAME

NA

8. FARM OR LEASE NAME **Read 2**
Stevens, Inc. Fed. "S"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Haystack-Cisco

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T-6-S, R-27-E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

1. OIL ☐ GAS ☐ OTHER **DRY**
WELL WELL

2. NAME OF OPERATOR
SHENANDOAH OIL CORPORATION

3. ADDRESS OF OPERATOR
702 V&J Tower Bldg, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FS & 2310' FBL

14. PERMIT NO.

-

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3831.1 GR, 3842.1 KB, 3841.1 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

**Verbal approval to plug and abandon was given Feb. 21, 1972, by
Mr. Leon Beekman, USGS, New Mexico.**

Plugging procedure as follows:

TD 6210
Spot 15 sx cmt. plug from 6080-5980
Spot 35 sx cmt. plug from 4980-4880
Spot 35 sx cmt. plug from 2500-2400
Spot 35 sx cmt. plug from 1450-1350
Spot 5 sx cmt. plug top of 8-5/8" csg.

Cut off, weld plate and set dry hole marker.
Completed at 4:30 PM, Texas time, February 23, 1972

RECEIVED

JUL 27 1972

G. C. C.
ARTESIA, OFFICE

RECEIVED

FEB 25 1972

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Billy Gover
BILLY GOVER

TITLE

Dist. Supt.

DATE

February 24, 1972

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUL 26 1972

R. L. Beekman
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.