

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 12 1972

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6428-1	
7. Unit Agreement Name	
8. Farm or Lease Name State	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Mountain States Petroleum Corporation
3. Address of Operator P.O. Box 1936 Roswell, New Mexico 88201
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 20 TOWNSHIP 4 South RANGE 27 East NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3908 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

June 7, 1972 TD 6440 ^{to} Plugged with Halliburton type "H" cement with plugs set as follows, as per OCC instructions:

35 SXS 6300-6400
35 SXS 5650-5750
35 SXS 4350-4450
35 SXS 2250-2350
35 SXS 1170-1270 in and out of 8-5/8" csg.

Will notify when surface marker set and location cleaned for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>KC Hansen</u>	TITLE <u>Geologist</u>	DATE <u>June 9, 1972</u>
APPROVED BY <u>W. A. Gressitt</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>JUN 12 1972</u>

CONDITIONS OF APPROVAL, IF ANY: