

UNITED STATES M. O. C. C. COPY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYForm Approved
Budget Bureau No. 42-R1424LEASE DESIGNATION AND SERIAL NO.
Midwest Federal 0223200

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for each proposal.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		2. NAME OF OPERATOR R. L. Force		3. ADDRESS OF OPERATOR 3700 First National Bank Bldg., Dallas, Texas 75202		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FSL & 660' FEL, Sec. 9, T14N, R28 E, Chaves County, New Mexico		5. LEASE DESIGNATION AND SERIAL NO. Midwest Federal 0223200		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
14. PERMIT NO. 12-14-1972		15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR-3570 DE 3576		7. UNIT AGREEMENT NAME		8. FARM OR LEASE NAME Midwest Federal		9. WELL NO. 1		10. FIELD AND POOL, OR WILDCAT Sams Ranch	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T14S, R28E, Hagerman Area		12. COUNTY OR PARISH Chaves		13. STATE New Mexico		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Spot 20 sack cement across perforations at 1713-16; 1698-1700. If pipe recovered below Queen at 1080' will set 100 ft. plug across Queen formation, 25 pound of gel per barrel heavy mud will be spotted between these plugs; 100' plug across the base of the 8-5/8" surface pipe at 252'; 20 foot cement plug in the top of the surface pipe. 4 inch diameter by 4 feet above surface dry hole marker with well description and location.

RECEIVED

DEC - 3 1973

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 11-27-1973

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

*See Instructions on Reverse Side