

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-005-60527

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

O'Brien Dering #2

8. Well No.

1

9. Pool name or Wildcat

Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

M. E. W. Enterprise

3. Address of Operator

300 S. Kentucky Roswell, N.M. 88203

4. Well Location

Unit Letter C : 660 feet from the north line and 1980 feet from the west line

Section

17

Township 8S

Range 29E

NMPM

County Chaves

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

4000 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. CIBP set above existing plugs at 2791', pump 20' cement cap & 35' cement on CIBP. plug 50' below 8 7/8 surface csg shoe at 243' pump 50' above & 50' below w/ cement. TAG w/ mud displace between 2791 & 293', displace hole to surface & pump

10' surface cement plug. Install 4' dry hole marked

* Perf. 5 1/2" csg to 30'. Circulate cement to surface.

Job completed before 8-1-01

* Perforate 5 1/2" casing to 1750'. Squeeze a 100' cement plug

Inside & Outside 5 1/2" casing. TAG

* Brine Gel between all cement plugs.

Notify N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Russell White

TITLE

Owner

DATE 5-8-01

Type or print name

(This space for State use)

Telephone No.

APPROVED BY

Steve Stillipell

TITLE Envr. Eng. Spec. I

DATE 5/14/2001

Conditions of approval, if any: