

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 Sout First, Artesia, NM 88210
District II
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

CISF
Op

Form C-103
Revised March 25, 1999

WELL API NO. 30005-60533
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Twin Lakes San Andres Unit
7. Well No. 38
8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> Injection
2. Name of Operator Concho Oil & Gas Corp. /
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701
4. Well Location Unit Letter <u>I</u> : <u>1650</u> Feet from the <u>South</u> line and <u>990</u> feet from the <u>East</u> line Section <u>36</u> Township <u>8S</u> Range <u>28E</u> NMPM Chaves County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3956 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully requests approval to plug and abandon the TLSAU #38 well according to the following procedure:

1. Notify NMOCD Artesia 24 hrs prior to commencement of procedure.
2. Set ~~150'~~ cmt plug from ~~2550-2700'~~ WOC. Tag. 220 2500-2720
3. Circ hole w/ mud.
4. Set 100' cmt plug @ 1935-2035'.
5. Perf csg @ 1585' & set 100' plug @ ~~1535-1635'~~ 1400 to 1500 Inside & Outside csg
6. Perf csg @ 830' & set 100' plug @ 780-880'. Inside & Outside csg
7. Perf csg @ 120'. Circ cmt from 170' to surface. Inside & Outside csg.
8. Cut off wellhead & install dry hole marker.

RECEIVED
OCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathe TITLE Production Analyst DATE 9-28-01

Type or print name Terri Stathe Telephone No. 915/681-7443

(This space for State use)
APPROVED BY [Signature] TITLE Field Rep DATE 10-10-01

Conditions of approval, if any: