STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT

ENGT AND MINACHMED DE		
40. 07 COPICS RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE	11	/
U.S.O.S.		
LAND OFFICE	1	
OPERATOR	1/	ł

JIL CONSERVATION DIVISION P O BOX 2088

Form C-103

DATE JUN 0 1 1981

DISTRIBUT	SANTA FE, NEW MEXICO & BEST VED	Kenized 10-1-10			
SANTA FE	· · · · · · · · · · · · · · · · · · ·	5a. Indicate Type of Lease			
FILE					
U.S.O.S.	JUN 0 1 1981				
OPERATOR		5. State Oil & Gas Leuse No.			
OF ENATOR					
	CHIEDRY HOTICES AND DEPORTS ON WELLS				
IND NOT USE	SUNDRY NOTICES AND REPORTS ON WELLS				
(50 40. 021	THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPLH OR PLUE SACK TO A DIRECTOR OF THE USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name			
🗂	CAS (
WELL X	WELL OTHER-	8. Farm or Lease Name			
tiame of Operator					
Stevens (Oil Company 🗸	O'Brien 'N'			
Address of Operati		9. Well No.			
	x 2203, Roswell, New Mexico 88201	2-Y			
	Twin Lakes-San Andres				
. Location of Well	Assoc.				
UNIT LETTER	M 540 FEET FROM THE South LINE AND 480 FEET FROM	mmmininn			
We					
THE	ST LINE, SECTION 32 TOWNSHIP 8-S HANGE 29-E NMPM.				
mmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County			
	3974.7 GR, 3979.7 KB	Chaves ()()()			
7/1/1/1/1/		. D			
٠ (.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data			
	NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:			
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING			
PERFORM REMEDIAL	CONVENCE DRIVING OPNS.	PLUG AND ABANDONMENT			
TEMPORARILY ABAND	CASING TEST AND CEMENT JOB				
PULL OR ALTER CASH	other Perforations and	d treatment			
	OTHERICITOLUCAOINO COM				
OTHER					
the state of starting any proposed					
. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
WORK) SEE HUL	E 1103.				
	a 1 B 2 : :: 0 5/0!! 20// enging cot at 130! w/125 sa	cks Class "C" and			
5-6-81	-6-81 Spud. Ram 3 joints 8 5/8" 20# casing, set at 130' w/125 sacks Class "C" and				
	3% calcium chloride. WOC 24 hrs. Pressured up to 1000# fo	1 Jo mail., neid.			
		. 202/1/200			
5-17-81	5-17-81 TD 2950'. Ran 73 joints 4 1/2" 9.5# casing, set in cement at 2924' w/200				
sacks self stress and 2% calcium chloride. WOC 24 hrs. Pressured up to					
1000# for 30 min., held.					
	1000% 101 30 matry 11020				
r 00 01	Demformation, 2806 5, 7, 8, 5, 9, 9, 5, 2823, 5, 24, 26, 26, 5, 2	7, 29.5, 30,			
5-20-81	5-20-81 Perforated: 2806.5, 7, 8.5, 9, 9.5, 2823.5, 24, 26, 26.5, 27, 29.5, 30,				
	30.5, 31, 31.5, 32. Spot acid at 2829'.				
		1			
5-21-81	Acidized w/7,000 gals 28% acid. Ran 88 joints of 2 3/8" tu	bing, set at			
	2698'.				
	•				
	•				
/	1				
	that the information above is true and complete to the best of my knowledge and belief.				
8. I hereby certify	1/1/				
1/2	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	r 00 01			
*16NED #//42	MILE TITLE Owner	_ BATE <u>5-28-81</u>			
	1/10				

SUF SRVISOR, DISTRICT, H