NH OLL COMS. COMMISSION Drawer DD Artesia, M

UNITED STATES									
DEPARTMENT	OF	THE	INTERIOR						
GEOLOGICAL SURVEY									

COMMED STATES	Budget Bureau No. 42-R1424							
COMMUNICO STATES	5. LEASE							
DEPARTMENT OF THE INTERIOR	NM-36652							
BEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME							
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME							
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME							
1. oil ☐ gas ☑	Barn Federal							
well well other	9. WELL NO.							
2. NAME OF OPERATOR 1	- 4							
Mesa Petroleum Co.	10. FIELD OR WILDCAT NAME							
3. ADDRESS OF OPERATOR	West Pecos Slope Abo							
P. O. Box 2009 / Amarillo, TX 79189	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA							
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17								
below.)	SEC. 13, T8S, R22E							
AT SURFACE: 1980' FSL & 1650' FEL	12. COUNTY OR PARISH 13. STATE							
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	Chaves New Mexico							
- Jame	_ 14. API NO.							
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,								
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)							
DECLIFET FOR APPROVAL TO: CHROCOLIENT DEPORT OF	3985.5' GR							
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:								
TEST WATER SHUT-OFF FRACTURE TREAT	## #B 00							
SHOOT OR ACIDIZE	ROUL SECTION AND ADDRESS OF THE PROPERTY OF TH							
REPAIR WELL	(NOTE: Report results of multiple completion or zone							
PULL OR ALTER CASING	change on Form 9-3801 rm							
MULTIPLE COMPLETE	= =							
CHANGE ZONES	14 14 14 14 14 14 14 14							
ABANDON* X (other)								
(Other)								
17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta	te all pertinent details, and elve persent dates							

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is directionally drilled, give subsurface focations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon subject well as follows:

- Set CIBP @ 2655' w/ 35' cmt (Abo perfs 2703' 3223'
- Set 25 sx plug from 1646' to 1546' (8 5/8" @ 1596').
- Set 10 sx plug from 150' to surface.
- Install Dry Hole marker.

RECEIVED BY

SEP 14 1983

O. C. D. ~ ARTESIA, OFFICE

XC:				EN RCDS, LL, PART		MAT	CONT,	GAS	CONT,	RES	ENG,	PROD	RCDS (1	FILE)
Subsurfa	ce Safe	ety Valve	e: Manu.	and Type							s	et @		Ft.
	0 1	n	Tark	going is true		1//	egulat pordin	ory ator	DATI	.	8-8-	83		
		. 841		(This space f	or Fede	ral or Stat	e office	use)					
APPROVE CONDITIO	NS OF	APPROV	ETER V	V. CHESTI	ER TITLE				DA	TE	 			

