	NAUTER OTATE	:e	5. LEASE	No. 42-R1424
	UNITED STATE		5. LEASE NM-23264	<u>v, ≰ ÷</u>
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDR	Y NOTICES AND REP	ORTS ON WELLS	7. UNIT AGREEMENT NAME	
not use this ervoir. Use F	s form for proposals to grill or teve orm 9–331–C for such proposals.)	Childrable Wilk to a differe	8. FARM OR LEASE NAME Salt Federal	
. oil □ □		B 27 1986	9. WELL NO.	
Mesa		O. C. D. RTESIA, OFFICE	10. FIELD OR WILDCAT NAME West Pecos Slope Ab	0
ΡO	S OF OPERATOR Box 2009 / Amarillo	o, Texas 79189	11. SEC., T., R., M., OR BLK. AN	
	ON OF WELL (REPORT LOCAT	ION CLEARLY. See space	Sec. 5, T8S, R23E	
below.) AT SUR	FACE: 795' FSL & 1833	5' FEL	12. COUNTY OR PARISH 13. S	TATE
ΑΤ ΤΟΡ	PROD. INTERVAL: Same		Onaves	ew Mexico
AT TOT	AL DEPTH: Same		14. API NO.	
5. CHECK REPORT	APPROPRIATE BOX TO IND	ICATE NATURE OF NOTIO	E, 15. ELEVATIONS (SHOW DF, M 4117.8' GR	(DB, AND WD)
FOUEST F	OR APPROVAL TO: SU	JBSEQUENT REPORT OF:	L	2
			200	a di
RACTURE	TREAT 🔄		ISY ISY	
HOOT OR	ACIDIZE		(NOTE: Report results of multiplied	empletion of the
EPAIR WE			change on Form 9-33	
NULTIPLE	COMPLETE 📃			33 2
HANGE Z				
BANDON*		<i>د</i>		
			Of	pertinent dates.
17. DESCR includi measu	IBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo	or all markers and zones pe	state all pertinent details, and give is directionally drilled, give subsurfa- tinent to this work.)*	pertinent dates, ce locations and
17. DESCR includi measu	IBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol	or all markers and zones pe lows:	tinent to this work.)*	pertinent dates, ce locations and
17. DESCR includi measu	IBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol	or all markers and zones pe lows: th 35' cement on	OP.	pertinent dates, ce locations and
17. DESCR includi measu	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol Set CIBP @ 2925' wi	th 35' cement on the stress of	op.	
17. DESCR includi measu	IBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl	th 35' cement on ug from 1510' to ug from 150' to s	op.	Prist I
17. DESCR includi measu	BE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad	th 35' cement on ug from 1510' to enhead.	op.	Prist I
17. DESCR includi measu	BE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole	th 35' cement on ug from 1510' to enhead. marker.	op.	Post 7 3-23
17. DESCR includi measu	BE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths fo was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad	th 35' cement on ug from 1510' to enhead. marker.	op.	Prist I
17. DESCR includi measu Well	BE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker.) hours, 11-14-83.	op. 410'. Irface.	Post I 3-23 PrM
17. DESCR includi measu Well	BE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker.) hours, 11-14-83.	op. 410'. Irface.	Post I 3-23 PrM
17. DESCR includi measu Well Well XC:	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400 BLM-R(0+6), CEN RCI ce Safety Valve: Manu. and Typ	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker. hours, 11-14-83. DS, ACCTG, MAT CON PARTNERS, MIDLA	op. 410'. arface. I, GAS CONT, RES ENG, PRO ND, ROSWELL Set @	Post I 3-23 PrM
17. DESCR includi measu Well Well XC: Subsurfac	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400 BLM-R(O+6), CEN RCI ce Safety Valve: Manu. and Typ	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker. hours, 11-14-83. DS, ACCTG, MAT CON PARTNERS, MIDLA	T, GAS CONT, RES ENG, PROND, ROSWELL Set @ -	Post I 3-23 PrM
17. DESCR includi measu Well Well XC: Subsurfac	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400 BLM-R(0+6), CEN RCI ce Safety Valve: Manu. and Typ	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker. D hours, 11-14-83. DS, ACCTG, MAT CON PARTNERS, MIDLA itrue and correct REGULAT	T, GAS CONT, RES ENG, PROND, ROSWELL Set @ - ORY ATOR DATE <u>11-18-83</u>	Post I 3-23 Pr/M DD RCDS(FILE
17. DESCR includi measu Well Well XC: Subsurfac	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400 BLM-R(0+6), CEN RCI ce Safety Valve: Manu. and Typ reby certify that the foregoing is R. F. Mathies	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker.) hours, 11-14-83. OS, ACCTG, MAT CON PARTNERS, MIDLA strue and correct REGULAT 	T, GAS CONT, RES ENG, PRON ND, ROSWELL Set @ ORY ATOR DATE 11-18-83	Post 7 3-23 Pr.M DD RCDS(FILE
17. DESCR includi measu Well Well XC: Subsurfac 18. here SIGNED	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400 BLM-R(0+6), CEN RCI ce Safety Valve: Manu. and Typ eby certify that the foregoing is R. F. Mathies	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker.) hours, 11-14-83. OS, ACCTG, MAT CON PARTNERS, MIDLA true and correct REGULAT 	T, GAS CONT, RES ENG, PRONT, RES ENG, PRONT, RES ENG, PRONT, ROSWELL Set @ ORY DATE 11-18-83 tate office use) DATE APPROV PETER W. CH	Post I 3-23 PKH DD RCDS(FILE Ft ED TESTER
Includi measu Well XC: Subsurfac 18. here SIGNED	TIBE PROPOSED OR COMPLE ng estimated date of starting red and true vertical depths for L was plugged as fol Set CIBP @ 2925' wi Set 25 sx cement pl Set 10 sx cement pl Cut off 8 5/8" brad Installed dry hole Well is P&A'd, 1400 BLM-R(0+6), CEN RCI ce Safety Valve: Manu. and Typ eby certify that the foregoing is R. F. Mathian	or all markers and zones pe lows: th 35' cement on ug from 1510' to ug from 150' to si lenhead. marker.) hours, 11-14-83. OS, ACCTG, MAT CON PARTNERS, MIDLA strue and correct REGULAT 	T, GAS CONT, RES ENG, PROND, ROSWELL Set @ - ORY ATOR DATE <u>11-18-83</u>	Post T 3 - 23 $P \neq H$ DD RCDS (FILE DD RCDS (FILE FT ED TESTER 1986.

- ----