## STATE OF NEW MEXICO MERGY AND MINERALS DEPARTMENT

we, or corice acceives	İ	
DISTRIBUTION		T
SANTA PE	7	
FILE	$\prod_{i}$	Z
U.S.G.S.		
LAND OFFICE		I
OFERATOR	1	Ī

## OIL CONSERVATION DIVISION

Form	C - 1	03	
Revis	ed	10-	1 - 78

Se er torite setti	<u> </u>	1	THE CONSER		V.13101V		Form C-103
DISTRIBUTION	<u> </u>	P. O. BOX 2088				Revised 19-1-7	
SANTA PE	<del></del>	4	SANTA FE, N				
FILE				J	UN 18 1091	Sa. Indicate T	· ·
U.S.G.S.		4				State	Fee X
OFERATOR		· ·			0.60	5. State Off 6	Gas Lease No.
OFERATOR		J		ė, s	TTUA, OFFICE		
					C. 1801. 1 Co. 1 1802.	mm	
(DO NOT USE THI	SUNDR	Y NOTICES	S AND REPORTS	ON WELLS	RENT RESERVOIR.		
	USE "APPLICAT	ION FOR PERMIT	T _ " (FORM C-101) FOR	SUCH PROPOSALS.)		7. Unit Agree	ment Name
oir ( <u>\( \bar{V} \)</u>	6A8 []						
	were L	OTHER-				8. Farm or Le	and Mana
Name of Operator						i	
Stevens Oi	il Company	<b>7</b> /					len ''L''
. Address of Operator						9. Well No.	
P. O. Box	2203, Ros	swell, Ne	w Mexico 8820	l		1 7	7
Location of Well						1 10. Field and	Pool, or Wildcat
	14	650	Nove	⊢h	220	), A Twin Lake Associ	s-San Andres
UNIT LETTER E		))U	ET FROM THENOT	LINE AND	FEET	777777 1000	mmmi
		_	^		00 =		
THE West	LINE, SECTI	он	TOWNSHIP9.	-S RANGE _	<u> 29-E</u> ∗	MPM. (	
	*******	~~~~					<i>…\\\\\</i>
		11/1/1/15	. Elevation (Show whe	ther DF, KI, GR, e	etc.)	12. County	
			3961' GR. 3966	5 KB		Chaves	
U,	Check		e Box To Indicat		orice. Report or	Other Data	
N.C	TICE OF I			1		ENT REPORT C	)F:
NC	TICE OF II	ATENTION	10:	1	3003240	2	
LRFORM REMEDIAL WORL	· 📙		PLUG AND ABANDON	REMEDIAL WO	ল্ <u>ক</u>		TERING CASING
LMPORARILY ABANDON					TILLING OPNS.	PL:	UG AND ABANDONMENT
BEL OR ALTER CASING			CHANGE PLANS	CASING TEST	AND CEMENT JOB	1 m	
				OTHER	<u>Perforations</u>	and Treatmen	rt[ <u>&gt;</u>
OTHER							
		perations (Clea	arly state all pertinen	details, and give	pertinent dates, incli	iding estimated date	of starting any propose
work) SEE RULE 11	103.						
			. 0 5/011 00				051 /
6-4-81			nts 8 5/8" 20 <sub>7</sub>				
			C'' and 1% calo			rs. Pressure	e up
	to 1000#	# for 30 1	minutes loggir	ng no pressu	re decrease.		
6-11-81	Ran 73 i	ioints 4	1/2" 9.5# cast	ing, set in	cement at 290	00' w/75 sack	cs Class "C"
• === <b></b>	and 1% o	calcium cl	hĺoride, follo	wed by 125	sacks self st	ress and 2%	calcium
	chloride	- WOC 1	8 hrs. Pressi	ired up to 1	000# for 30 r	nin logging	no pressure
	decrease		o ind. Treboo	area ap co r	000# 101 30 1	1066116	no pressure
	uecrease	Ξ•					
( 10 01	D .	1 0760	r 70 70 r (	)77/ F 75	7F F 0700 F	01 01 5	707 07 5
6 <b>-12-</b> 81	reriorat	led 2/69.	5, 70, 70.5, 2	2//4.5, /5,	75.5, 2/80.5	, 81, 81.5, 4	2/9/, 9/.5
			, 2808.5, 09,				
	Acidize	w/9000 g	als 28%. Ran	90 joints 2	3/8" tubing	, set at 2654	1.
	•	Ü	٠	-	O		
			·				
•		•					