## STATE OF NEW MEXICO HERGY AND MINERALS DEPARTMENT

we, or corise heccives	1	
NOITE BIRTZIO		
SANTA FE		
FILE		1
U.\$.0.\$.		
LAND OFFICE		
OPERATOR		

## OIL CONSERVATION DIVISION

Form	C - 1	03		
Revis	e d	10-	1 -	78

40.07 (0711)		p	O. BOX 2088			Form C-103
DISTRIB	TTION		I, NEW MEXICO			Revised 10-1-78
SANTA FE		SANTAFI			5a, Indicate Type	of l wise
FILE				ULS THE		For X
U.S.O.S.					State	
OPERATOR				(A. C. D	5. State Oil & Ga	s Leone No.
CFERRIOR				The second of th	•	
					MITTI	
	SUNDRY	NOTICES AND REPO	RISON WELLS	BENT RESERVOIR.		
ופט זמא סמן	UTA TOT MOT STAT JEU	OSALS TO FRILL ON TO DELPTH	1) FOR SUCH PROPOSALS.)		7. Unit Agreemen	7 Name
					7. Ollie Kiji etimen	
مال 🔀	GAS WELL	OTHER+				
tiarne of Operato:					8. Farm or Lease	
Ω	ating Corn	/			O'Brien	''L''
Address of Opera	erating Corp.	V			9. Well No.	
		M 2000	1		8	
P. O. Box	2203, Roswell	, New Mexico 8820	L		in Field and Po	ol, or Wildcat
. Location of Well			•	1650	Twin, Lakes	-San Andres
	F 16	550 FEET FROM THE	North LINE AND_	1600 FEET FAON	ASSOC.	mmm
UNIT LETTER	· · · · · · · · · · · · · · · · · · ·					
Most		N TOWNSHIP	9S	29E NMPM		
THE WEST	LINE, SECTIO	N TOWNSHIP	MANGE .		XIIIIIII	
~~~~~~~~	mm	TTTT 16 Flavortion (Sho	w whether DF, RT, GR,	etc.)	12. County	
				,	Chaves	
	(()))))))	3996.1 GR,			.1	(1)111111111
9.	Check A	Appropriate Box To Inc	dicate Nature of N	otice, Report or Ot	her Data	
	NOTICE OF IN		- 1	SUBSEQUEN	T REPORT OF:	
	NOTICE OF IN	TENTION TO:				
			<u></u>		ALTE	TING CASING
PERFORM REMEDIA .	WORK	PLUG AND ABA	I	F		
LEMPORARILY ABANG	OON		i i	RILLING OPHS.	PLUG	AND ABANDONMENT
PULL OR ALTER CAS	ING	CHANGE PLANS	CASING TEST	AND CEMENT JOB	<b>.</b>	ſ <del>⊽</del>
			OTHER	Perforations &	Treatment	<u>[X</u>
OTHER						
. Describe Propo	sed or Completed Op	erations (Clearly state all pe	rtinent details, and give	pertinent dates, includin	g estimated date of	starting any proposed
work) SEE RU	LE 1103.					
				mont at 28/1/1 to	ith 200 cacl	70
6-19-81	Ran 71 joi	nts 4 1/2" 9.5# ca	sing, set in ce	ment at 2044 w	71 LL 200 Sac	· · ·
	calf stres	s and 2% calcium c	hloride. Press	sured up 1000# I	or 30 minute	es
	logging no	pressure decrease	. WOC 18 hrs.			
	1065216 110	F				
c 00 01	D. C d	2702, 20.5, 03, 2	713 13 5 14	14.5. 2716. 16.	5. 17. 17.5	•
6-23-81	Perforated	2702, 20.3, 03, 2	06 065 07	14.5, 2720, 20.	· • · · · · · · · · · · · · · · · · · ·	,
	2/19, 19.5	, 20, 2725, 25.5,	20, 20.3, 27.			
			07001	1 1000	nn1- 209	
6-24-81	Ran 85 joi	nts 2 3/8" tubing,	set at 2/22'.	Acidized W/800	ou gais 20%.	
0 - 1 0 -	3	_				
	•					
	•					

5. I hereby fertily that the information above is true and complete	TITLE	Owner	DATE_	7-7-81
	T17LE	THE ENGINEE SISTERICE IT	DATE	JUL 1 4 1981