STATE OF NEW MEXICO ERGY AND MINERALS DEPARTMENT

HO. OF COPIES RECEIVED	1	
DISTRIBUTION	1	T
SANTA FE	17	1
FILE		1
U.\$.0.\$,		
LAND OFFICE		
OPERATOR		1

OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088		Form C-103
SANTA FE	SANTA FC, NEW N	MEXICO 87501	Revised 10-1-7
U.S.O.S.	·		5a. Indicate Type of Lease
LAND OFFICE			State X Fue
OPERATOR			5. State Oli & Gas Lease No.
h-191-1			LG-4354
SUNDRY NO	OTICES AND REPORTS ON W	FILS	THITTINING TO
UD HOT USE THIS FORM FOR PROPOSAL USE "APPLICATION FO	IS TO DRILL OR TO DECPEH OF PLUG BAC DR PERMIT —" (FORM C-101) FOR SUCH F	A TO A DIFFERENT HESERVOIR.	
OIL GAS X O	THER•	MECK IA BES	7, Unit Agreement Name
ame of Operator		0110 a x 3004	8. Furm or Lease Name
Yates Petroleum Corpor	ation /	AUG 1 3 1981	Cockleburr "RD" State
dress of Operator		يوني يحر	9. Well No.
207 South 4th St., Art	esia, NM 88210		1
ocation of Well			10. Field and Pool, or Wildcat
M 810	South South	LINE AND SEET E	Und. Abo
THE West LINE, SECTION	17 TOWNSHIP 7S	RANGE 25E NM	
	15. Elevation (Show whether DF		12. County
	3806.21	GL	Chaves
Check Appre	opriate Box To Indicate Nat	ture of Notice. Report or	Other Data
NOTICE OF INTEN			ENT REPORT OF:
	ļ		
FORM HEMEDIAL WORK	PLUG AND ABANDON R	REMEDIAL WORK	ALTERING CASING
PORARILY ABAHDON	, c	OMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
COR ALTER CASING	CHANGE PLANS	ASING TEST AND CEMENT JOB	
		the state of the s	ing, Perforate, Treat X
THER			(A)
Describe Proposed or Completed Operatio work) SEE RULE 1703.	ons (Clearly state all pertinent details	s, and give pertinent dates, includ	ling estimated date of starting any proposed
•	5 / 1 /011 O 5 // (/O501)		
TD 4050' - Ran 102 jts of	r 4-1/2" 9.5# (4052') o	of casing set at 4050	'. Cemented w/370
sacks 50-50 Poz, .6% CS9	, .3% TF4 & 3% KCL. PD	7:30 PM 7-14-81. W	OC. WIH with wireline
Steel Strip and perforated	d 3732-3744' w/8 .50" h	oles as follows: 37	32, 33, 36, 37, 38, 42,
43, & 44'. Ran 4-1/2" Gu	iberson packer on 119 j	ts 2-7/8" tubing. To	ested tubing to 6000#
OK. Spotted 250 gals of	7-1/2% NEFE acid. Set	packer at 3698'.Sai	nd frac'd perforations
3732-3744' (via tubing) v	w/1000 gals 7-1/2% NEFF	acid. Followed by	20000 gals Vorsa gal
1300 gals CO2 and 40000#	sand (10000# 100 mesh	& 30000# 20/40 sand)	Recovered load.
Well stabilized and flower	ed 40 psi on 5/16" chok	a = 100 me fnd	. Recovered load.
werr bestrifted and from	ed 40 psi on 5/10 chok	e - 100 mcrpa.	
	•		
•			
hereby certify that the information above	is true and complete to the best of m	y knowledge and belief.	
•	•		
And the second	Fnoi	neering Secretary	Q. 7 O1
of Willa	TITLE Engli	neering Secretary	BATE 8-7-81
Was Inca	STIPE	RVISOR DISTRICT TO	AUG 1 8 1981