

7-21-83

H.W. Pace, Barnburner #1 L-16-8-26 P & A

Tag cement plug @ 398 ft. Set cast iron bridge plug @ 70 ft.
Circulated cement to surface. Set marker and cut off tie down.

B.W. Weaver