Sabnat 2 Copics To Appropriate District Office District D	_	C12/L	
WELL APINO. 1025 Number Dr., 1040bb, NM 89240 OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NM 87505 S. Indicate Type of Lease STATE FEE S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee NM 87505 S. State Oil & Cas Lease No. State Fee Nm 87505 S. State Oil & Cas Lease No. State Fee Nm 87505 S. State Oil & Cas Lease No. State Fee Nm 87505 S. State Oil & Cas Lease No. State Oil & Cas Corp. S. Well No. State Oil & State Oil & Cas Corp. S. Well No. State Oil		exico Form C-103	
District II 15. South First, Artesia, NM 88210 District II 2040 South Pacheco Santa Fe, NM 87505 Santa Fe, NM 87505 SINDRY NOTICES AND REPORTS ON WELLS CO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PREMIT (FURM C-10) FOR SUCH NOTICE OF ROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PREMIT (FURM C-10) FOR SUCH NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ARE IN PROPOSED OF COMMENT OF PULL OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. ARE IN PROPOSED OF THE WITCH ON THE PULL OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. ARE IN PROPOSED OF THE WITCH OR SUBSEQUENT REPORT OF THE WITCH OR SUBSEQUENT REPORT OF THE WITCH OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. ARE IN PROPOSED OF THE WITCH OR ALTER RETURN WELL TO PULL OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. ARE IN THE WITCH OR ALTER RETURN BY THE WITCH OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. ARE IN THE WITCH OR ALTER RETURN WELL TO PULL OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND COMMENT ARE INCIDENT ARE INCIDENT AND CEMENT JOB OF THE WITCH OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND COMMENT ARE INCIDENT ARE INC	District I Energy, Minerals and Nat		
Sunday S		20005 61022	
South Peaker, NM 8740 South Fe, NM 87505 South Fe, NM 87505 South Peaker, NM 87505 Sou	811 South First, Artesia, NM 88210 OIL CONSERVATION	heco 5. Indicate Type of Lease	
2000 South Pacheco, Santa Fe, NM 87505 2000 South Pacheco, Santa Fe, NM 87505 2000 South Pacheco, Santa Fe, NM 87505 2000 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUJO BACK TO DEFFERN TRESERVOR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH The Concho Oil & Gas Corp. 2. Name of Operator 2. Name of Operator 3. Address of Operator 10 W. Louisians Ste 410, Midland, Tx 79701 3. Address of Operator 10 W. Louisians Ste 410, Midland, Tx 79701 4. Well Location 4. Well Location 4. Well Location 5. Section 6. Township 98 Range 29E NMPM Chaves County 5. Section 6. Township 98 Range 29E NMPM Chaves County 6. Elevation (Show whether DR, RKB, RT, GR, etc.) 6. SUBSEQUENT REPORT OF: 6. PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ABANDON ABANDON COMPLETION COMPLETION 6. COMPLETION COMPLET	1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 8	STATE LI FEE X	
DONOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Welk Oil Well Gas Well Other Injection Of Concho Oil & Gas Corp. 3. Address of Operator 110 W. Louisiana Size 410; Midland, Tx 79701 4. Well Location Unit Letter P: 990 Feet from the South line and 990 feet from the East line Section 6 Township 98 Range 29E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3943 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLUL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB COMPLETION CHANGE PLANS ABANDON ABANDON CHANGE PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLUG AND ABANDON CHANGE PRILLING OPNS. ALTERING CASING COMPLETION CEMENT JOB OTHER: OTHER: CASING TEST AND CEMENT JOB OTHER: Return well to Production 11-26-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered the 35" to tag btim @ 2816". Strapped OOH & LD tybe. PU & THH w/ BP, MF, 2-3/8" x4 y perf sub, SN, & 84 jts used 2-3/8" the from #18 & 5 jts used the from yard. Total the above SN = 89 jts 2771'. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON. 11-28-01 RU Derrick WSU. POH w/ 50 – ½" rods & 10 – 5/8" rods to body break. SDON.	District IV	6. State Oil & Gas Lease No.	
Twin Lakes San Andres Unit Twin Lakes Can San Can S	SUNDRY NOTICES AND REPORTS ON WELL		
1. Type of Well	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) F	OR SUCH Twin Lakes San Andres Unit	
2. Name of Operator Concho Oil & Gas Corp. 3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701 4. Well Location Unit Letter P: 990 Feet from the South line and 990 feet from the East line Section 6 Township 98 Range 29E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3943 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING CASING ABANDON CHANGE PLANS COMPLETION CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPLETION CHANGE PLANS OTHER: Return well to Production OTHER: Return well to Production OTHER: Return well to Production 11-26-01 RU Derrick WSU. POH w/50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ½", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. Test: 8 BO, 108 BW. TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathern Telephone No. 8 16/88 7443 TITLE DATE 12-10: CT	1. Type of Welk	DO PECCI.	
Section South So	On wen		
Twin Lakes; San Andres (Assoc) Twin Lakes; San Andres Twin		dr.	
Well Location			
Unit Letter P: 990 Feet from the South line and 990 feet from the East line Section 6		13 02 01 Will Bures, Sun Tindres (12000)	
Section 6 Township 9S Range 29E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3943 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Return well to Production 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Detrick WSU. POH w/ 50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered they 35" to tag btm @ 2816'. Strapped OOH & LD they. PU & TIH w/ BP, MF, 2-3/8" x 4" perf sub, SN, & 84 jts used 2-3/8" to from #18 & 5 jts used they from yard. Total they above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ½", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem TITLE DATE DATE 12-5-01 Type or print name Terri Stathem TITLE DATE DATE 12-5-01 Type or print name Terri Stathem TITLE DATE DATE 12-5-01			
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3943 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Return well to Production 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered tbg 35' to tag btm @ 2816'. Strapped OOH & LD tbg. PU & TIH w/ BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" tbg from #18 & 5 jts used tbg from yard. Total tbg above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ½", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. Test: 8 BO, 108 BW. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE THILD THE Production Analyst DATE 12-5-01 Type or print name Terri Stathern Terri Stathern Telephone No. 916/688/7443 Telephone No. 916/688/7443 DATE 12-5-01 Type or print name Terri Stathern Terri Stathern Telephone No. 916/688/7443	Unit Letter P: 990 Feet from the South	and 990 leet from the Last inc	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Return well to Production 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered the 35" to tag brum @ 2816". Strapped OOH & LD the PU & TIH w/ BP, MF, 2-3/8" x 4" perf sub, SN, & 84 jts used 2-3/8" the from #18 & 5 jts used the from yard. Total the above SN = 89 jts 2771". SDON. 11-28-01 PU & TIH w/ 1.5" x 16" insert pump, 10 - 7/8", 44 - ½", & 56 - 7/8" rods, 1 - 7/8" x 8" & 1 - 7/8" x 4" pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or psint name Terri Stathem Telephone No. 9 16/68 7443 The APPPROVED BY TITLE DATE 12-6-01 DATE 12-6-01 DATE 12-6-01		MATERIAL STATE AND	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Return well to Production 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered the 35" to tag brum @ 2816". Strapped OOH & LD thg. PU & TIH w/ BP, MF, 2-3/8" x 4" perf sub, SN, & 84 jts used 2-3/8" the from #18 & 5 jts used the from yard. Total the above SN = 89 jts 2771". SDON. 11-28-01 PU & TIH w/ 1.5" x 16" insert pump, 10 - 7/8", 44 - ¼", & 56 - 7/8" rods, 1 - 7/8" x 8" & 1 - 7/8" x 4" pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Terri Stathem Terri Stathem Telephone No. 9 16/68 17443 This space for State use) APPPROVED BY TITLE DATE 12-5-01 DATE 12-5-01 DATE 12-5-01 DATE 12-5-01 DATE 12-5-01 DATE 12-6-01 DATE		PR, RKB, RT, GR, etc.)	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Return well to Production 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered bg 35' to tag btm @ 2816'. Strapped OOH & LD tbg. PU & TIH w/ BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" tbg from #18 & 5 jts used tbg from yard. Total tbg above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ½", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Telephone No. 9 16/68 17443 Telephone No. 9 16/68 17443 THILE DATE 12-5-01		lature of Notice, Report or Other Data	
TEMPORARILY ABANDON	NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PULL OR ALTER CASING	PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING	
OTHER: CEMENT JOB OTHER: Return well to Production 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 - ½" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered tbg 35' to tag btm @ 2816'. Strapped OOH & LD tbg. PU & TIH w/ BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" tbg from #18 & 5 jts used tbg from yard. Total tbg above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ½", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 9 16/68 17443 (This space for State use) APPPROVED BY TITLE DATE DATE 12-10-Ci	TEMPORARILY ABANDON ☐ CHANGE PLANS ☐		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 – ¼" rods & 10 – 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered tbg 35' to tag btm @ 2816'. Strapped OOH & LD tbg. PU & TIH w/ BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" tbg from #18 & 5 jts used tbg from yard. Total tbg above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 – 7/8", 44 – ¾", & 56 – 7/8" rods, 1 – 7/8" x 8' & 1 – 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 916/6847443 (This space for State use) APPPROVED BY TITLE DATE DATE 12-5-01	, 022 0.17		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 - ½/4" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered the 35' to tag btm @ 2816'. Strapped OOH & LD the PU & TIH w/ BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" the from #18 & 5 jts used the from yard. Total the above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ¾", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 916/6847443 (This space for State use) APPPROVED BY TITLE DATE DATE 12-6-01	OTHER:	OTHER: Return well to Production	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-26-01 RU Derrick WSU. POH w/ 50 - ¾" rods & 10 - 5/8" rods to body break. SDON. 11-27-01 FOH. LD rods & pump. Lowered tbg 35' to tag btm @ 2816'. Strapped OOH & LD tbg. PU & TIH w/ BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" tbg from #18 & 5 jts used tbg from yard. Total tbg above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ¾", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 9 4/684 7443 (This space for State use) APPPROVED BY TITLE DATE 12-10-Ci	12 Describe proposed or completed operations. (Clearly state all pe	ertinent details, and give pertinent dates, including estimated date	
FOH. LD rods & pump. Lowered the 35' to tag btm @ 2816'. Strapped OOH & LD the PU & TIH w/BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" the from #18 & 5 jts used the from yard. Total the above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - ¾", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst Terri Stathem Terri Stathem Telephone No. 9 16/68 7443 (This space for State use) APPPROVED BY TITLE DATE 12-10-C1			
FOH. LD rods & pump. Lowered the 35' to tag btm @ 2816'. Strapped OOH & LD the. PU & TIH w/BP, MF, 2-3/8" x 4' perf sub, SN, & 84 jts used 2-3/8" the from #18 & 5 jts used the from yard. Total the above SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 - 7/8", 44 - 1/4", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst Terri Stathem Terri Stathem Telephone No. 9 16/68 7443 (This space for State use) APPPROVED BY TITLE DATE 12-16-C1	11 26 01 RU Derrick WSU POH w/ 50 – 3/4" rods & 10 – 5/	8" rods to body break. SDON.	
SN = 89 jts 2771'. SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, 10 – 7/8", 44 – ¾", & 56 – 7/8" rods, 1 – 7/8" x 8' & 1 – 7/8" x 4' pony rods. Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 9 16/68 7443 (This space for State use) APPPROVED BY TITLE DATE 12-10-Ci	11-27-01 FOH. LD rods & pump. Lowered tbg 35' to tag btm @ 2816'. Strapped OOH & LD tbg. PU & TIH w/ BP,		
PU & TIH w/ 1.5" x 16' insert pump, 10 – 7/8", 44 – ¾", & 56 – 7/8" rods, 1 – 7/8" x 8' & 1 – 7/8" x 4' pony rods. Hung on beam return well to production. Test: 8 BO, 108 BW. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 9 16/68 7443 (This space for State use) APPPROVED BY		tbg from #18 & 5 jts used tbg from yard. Total tbg above	
Hung on beam return well to production. 12-02-01 Test: 8 BO, 108 BW. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 916/6817443 (This space for State use) APPPROVED BY TITLE DATE 12-10-0;	SIN = 89 Jts 2771 . SDON. 11-28-01 PU & TIH w/ 1.5" x 16' insert pump, $10 = 7/8$ ", 44	$-\frac{3}{4}$ ", & 56 - 7/8" rods, 1 - 7/8" x 8' & 1 - 7/8" x 4' pony rods.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 9 16/68 7443 TITLE DATE 12-10-01	Hung on beam return well to production.		
TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 916/68 7443 (This space for State use) APPPROVED BY TITLE DATE 12-5-01	12-02-01 Test: 8 BO, 108 BW.		
TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 916/68 7443 (This space for State use) APPPROVED BY TITLE DATE 12-5-01	ℓ		
TITLE Production Analyst DATE 12-5-01 Type or print name Terri Stathem Telephone No. 916/68 7443 (This space for State use) APPPROVED BY TITLE DATE 12-5-01		1	
Type or print name Terri Stathem Telephone No. 916/6817443 (This space for State use) APPPROVED BY TITLE DATE 12-10-01	I hereby certify that the information above is true and complete to the	best of my knowledge and belief.	
(This space for State use) APPPROVED BY TITLE DATE 12-10-01	SIGNATURE TITLE	Production Analyst DATE 12-5-01	
(This space for State use) APPPROVED BY TITLE DATE 12-10-01	Type or print name Terri Stathem	Telephone No. 916/684 7443	
ATTINOVED DI		1.10 PAGE 12-10-02	
	MITIKOTEDET		