STATE OF N		
WE OF COPIES RES	OH CONSERVATION DIVISION	
DISTRIBUT	B C BOX 3000	Form C-103
SANTA PE	SANTA FE, NEW MEXICO 8750FIVED	Revised 10-1-7
FILE	JANTA TE, NEW MEXICO 87301	Sa. Indicate Type of Leuse
U.S.O.S.		
LAND OFFICE		
OPERATOR		5, State Oil & Gas Lease No.
<u> </u>	O. C. D.	
(DO NOT USE T	SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE HIS FORM FOR PROPOSALS TO DRILL OR TO DECPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL X	GAB OTHER-	7. Unit Agreement Name
Name of Operator	WILL CONTRACTOR OF THE PROPERTY OF THE PROPERT	8. Farm or Lease Name
	perating Corporation	O'Brien 'L''
Address of Operator	cracing corporation y	9. Well No.
-	2203, Roswell, New Mexico 88201	13
1 ocation of Well		Twin Lakes-San Andres
		Assoc.
THE West	LINE, SECTION 6 TOWNSHIP 9S RANGE 29E NMPM	
~~~~	C) 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	<u> </u>
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3989.1 GR, <b>%</b> 994.1 KB	Chaves (1)
PURPORM REMEDIAL WO TEMPORABILY ABANDON TOUL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK	T REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT
	OTHER	L
OTHER		
7. Describe Proposed work) SEE RULE	or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including 1103.	g estimated date of starting any propose
7-18-81	Spud. Ran 3 joints 8 5/8" 20# surface casing, set in cement at 130" w/75 sacks Class "C", 2% CaCl. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.	
7-25-81	Ran 71 joints 4 1/2" 9.5# casing, set in cement at 2826' stress, 3% CaCl. WOC 18 hrs. Pressure up 1000# for 30 $\pi$ no pressure decrease.	w/200 sacks self inutes logging
	,	
	·	
		•
	•	