
Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Munerals and Natural Resources Department



DISTRICTI

OIL CONSERVATION DIVISION

WELL API NO.

P.O. Box 1980, Hobbs, NM 882		P.O. Box 2088		WELL ATTIO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 8	8210 San	a Fe, New Mexico	87504-2088 FEB -8 '90'	5. Indicate Type of Le	STATE FEE	$\overline{\mathbf{x}}$
DISTRICT III			HB -0 20	6 State Oil & Gos Lee		=
1000 Rio Brazos Rd., Aziec, NM 87410				6. State Oil & Gas Lease No.		
SHNDE	Y NOTICES AND	REPORTS ON WEL	LS: Line		7//////////////////////////////////////	<i>77)</i>
(DO NOT USE THIS FORM	FOR PROPOSALS TO	DRILL OR TO DEEPEN	OR PLUG BACK TO A	7. Lease Name or Uni	t Agreement Name	
•	IT RESERVOIR. USE " (FORM C-101) FOR SU	APPLICATION FOR PER CH PROPOSALS.)	IMIT*	Twin Lakes S	San Andres Unit	
. Type of Well: OIL WELL [X]	GAS WELL	OTHER				
Name of Operator	relopment Corpo	ration		8. Well No. 77.		
	eropment corpo	Tations		9. Pool name or Wilde	cat	
Address of Operator 1000 Louis	siana, Suite 29	000, Houston, T	X 77002	Twin Lakes Sa		
. Well Location	2310	South	33	O Feet From Th	West	
Unit LetterL	: Feet From	The South	Line and33	Feet From Th	e	Line
Section 6	Township	9S R an	nge 29E	NMPM Chaves	S Coun	ty
		. Elevation (Show whether i	DF, RKB, RT, GR, etc.)			
	//////////////////////////////////////	3994 1 KB 398		D (OI D	<u> </u>	
			Nature of Notice,	Report, or Other D		
NOTICE	OF INTENTION	TO:	St	JBSEQUENT REF	PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				AL	TERING CASING	
EMPORARILY ABANDON		GE PLANS	COMMENCE DRILL	ING OPNS PL	UG AND ABANDONMEN	т
					,	
ULL OR ALTER CASING	-11 to commisso		CASING TEST AND	n well to servi	ce	ראו
THER:	ell to service	X	OTHER:			_
12. Describe Proposed or Comp	leted Operations (Clearly)	nate all pertinent details, ar	nd give pertinent dates, is	ncluding estimated date of sk	irting any proposed	
1-15-90: WIH w	/88 its 2-3/8"	EUE tbg w/bull	plugged mud	anchor on btm o	f string hung a	t
2700	SN 0 2664'.	SDON.				
1_16_90: WIH w	/ a 2" x 1½" x	10' RWBC pump	on a $5/8'' \times 4$	' lift sub, 62	5/8" rods, 43 3	/4"
rods,	$1 \ 3/4" \times 6"$	1 3/4" x 4' por	ny rods on top	of the string.	Hung on beam.	
RDPU.	c1 1.					
1-18-90: Elec.	problems, lie	tu power out:	to tank hatte	rv.		
1-17-90: Made 1-18-90: Elec.	flowline conne problems, fie ed pumping uni		to tank batte	ry.		
^						
I hereby certify that the information	n above is true and complete t	o the best of my knowledge and	belief.			
()	la Cras	eller T	ne Productio	n Analyst		
SIGNATURE	la Crassian				TELEPHONE NO. 713/75	50-75
TYPE OR PRINT NAME /Linc	la Crossley					===
(This space for State Use)	ORIGINAL SIGNE	D BY				~
	MIME WILLIAMS				FEB 9 19	40
A TOTAL OF THE BY	SUPERVISOR, DIS	TRICT II T	TLE		_ DATE	