

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-005-61061

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Cibola Energy Corporation

3. Address of Operator

P.O. Box 1608, Albuquerque, NM 87103-1608

4. Well Location

Unit Letter D : 330 Feet From The North Line and 330 Feet From The West Line

Section 34

Township 11 S

Range 28E

NMPM

Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3655 GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-7-00 (1) Notified NMOCD-Phil Hawkins

(2) Set 4-1/2" CIBP @ 7637'.

(3) Dump bail 2-1/2 sx cement @ 7637-7601'.

3-3-00 (4) Circulate hole w/ 10# MLF @ 7600'.

(5) Spot 25 sx cement @ 7100', WOC & Tag TOC @ 6787'.

(6) Spot 25 sx cement from 5540 - 5179'

(7) Spot 25 sx cement from 5150 - 4789'

(8) Cut 4-1/2" csg. @ 2438'

3-9-00 (9) Spot 40 sx cement @ 2488', WOC & Tag TOC @ 2308'.

(10) Spot 35 sx cement @ 1560 - 1424'

(11) Spot 35 sx cement @ 455 - 319

(12) Circulate 10 sx cement 30 to Surface.

Will cut WH & deadmen, install dry hole marker, backfill pit & cellar. ASAP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Area Manager

DATE 3-15-00

TYPE OR PRINT NAME

Roger Massey

TELEPHONE NO. (915) 570-7087

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 14 2002