

HEYCO ✓

PETROLEUM PRODUCERS



HARVEY E. YATES COMPANY

P. O. BOX 1933

SUITE 300, SECURITY NATIONAL BANK BUILDING

505/623-6601

ROSWELL, NEW MEXICO 88201

RECEIVED

JAN 18 1983

O. C. D.
ARTESIA, OFFICE

January 17, 1983

New Mexico Oil Conservation Division
P. O. Box 2088
Santa Fe, NM 87501
Attn: Mr. Joe D. Ramey
Division Director & State Petroleum Engineer

Re: Seymour State Com #1 ✓
Unit E, Sec. 18, T-9S, R-27E
Chaves County, NM
Order No. R-7112 & Case No. 7658

Dear Mr. Ramey:

Please find attached a copy of the logs run on the captioned well which were required by Order No. R-7112 of Case No. 7658. Said procedure was witnessed by Mr. Mike Williams of the Artesia District office and myself.

As explained by the logging company operator, no evidence of crossflow was seen, nor production of any sorts from the perforations at 5926' to 5944'. We respectfully request commission approval for the current downhole assembly previously under question.

Upon approval, the required 4-point or Multi-point Back Pressure Tests and Packer Leakage Tests will be performed. If there is further need for additional information, please contact my office.

Sincerely yours,

Ray F. Nokes
Reservoir Engineer

RFN:dy

Enclosures

cc: Oil Conservation Division
Artesia, NM