	ATE OF NEW MEXICO	•	· · ·
	NO MINERALS DEPARTMENT	•	
		L CONSERVATION DIVISION	
	AFE	P. O. BOX 2088	Form C-103
FILE	s s	ANTA FE, NEW MEXICO STOT	Revised 10-1-78
U.S.C		•	Sa. Indicate Type of Lease
)	OFFICE	JUN 06 1983	State Fee X
OPE	ATOR		S. State Oil & Gas Lease No.
<b>-</b>		O. C. D.	J. Store OIL & Cas Lease No.
(0)	SUNUKT NUTICES A SUNUKT NUTICES A NOT USE THIS FORM FOR PROPOSALS TO DRILL USE "APPLICATION FOR PERMIT -	ND REPORTS ON WELLS ARTESIA, OFFICE	
01L W(LL	WELL A OTHER-	•	7. Unit Agreement Nome
Name of	•	· · ·	8. Farm or Lease liame
	CLEMENTS ENERGY, INC.		King 35 Com
Address	l Operator		9. Well No.
P. O. Box 20500, Oklahoma City, Oklahoma 73156			1 .
Location			
	J 1980	South 1000	10. Field and Pool, or Wildcat
VHIT LI	TTER FEET #	BOM THE SOUTH LINE AND 1980 FEET FRO	W. Buffalo Valley-Penn
	Fact	1/ 0	
THE	East LINE, SECTION 35	TOWNSHIP RANSE 26-E HMPL	//////////////////////////////////////
m			
//////	///////////////////////////////////////	eration (Show whether DF, RT, GR, etc.)	12. County
71111		3420' GR	Chaves ()
**	Check Appropriate B	ox To Indicate Nature of Notice, Report or O	
	NOTICE OF INTENTION TO		
		- SUBSEQUEN	TREPORT OF:
	<b>EV</b>		
TRFORM RE	MEDIAL WORK	LUG AND ABANDON REMEDIAL WORK	ALTERING CASING
IMPORARIL	A & & A & A & A & A & A & A & A & A & A	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
HEL ON AL	ER CASING	HANGE PLANS CASING TEST AND CEMENT JOB	
		OTHER	
-			
	· · · · · · · · · · · · · · · · · · ·		\$
- Describe	Proposed or Completed Operations (Clearly E RULE 1 103.	state all pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed
wang s		•	• • • • •
1.	Treat perfs 6925-7008' with	4,000 gals. 7-1/2% HCl with 1,000 SCF	Nitrogen with
	Surfactants.		
	•		
2.	Test		
	•		
3.	Pull tubing and perforate 6	772-78' and 6782-86'	
4.	Run tubing with packer and p	retrievable bridge plug set; BP @ appr	ovimately 68351
	and packer at 6700'+.	in the second seco	JAIMACELY 0055
		•	•
5.	Swah and toot porfs than the	$a = \frac{1}{2} - $	
5.	free with 15 000 cole Hell	eat with 2,000 gals. 7-1/2% HCl and if	results warrant
	That with 15,000 gais. Hall	iburton Pur-Gel with 25% Carbon Dioxid	e and 15,000# 20/40 sand.
ć		· · · · · · · · · · · · · · · · · · ·	•
6.	iest and if results warrant	pull RBP and run 2-3/8" tubing with p	acker set at 6700'.
	•		
I hereby	ertily that the information above is true and	complete to the best of my knowledge and belief.	
-	IN M		
+	11 Julen	•••	
· co <u>\</u>		Vice President - Operations	May 24, 1983
4 <u>1999</u> 1999 1999 1999		Original Signed By	
		Leslie A. Clements .	<b>.</b>
		Supervisor District II	11 IN A 6 1002