
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \							
Submit 3 Copies To Appropriate District	State of New Mexico		$c_{ico}$	Mo		Form C-	103
Office	Energy, Minerals and Natural Resources					Revised March 25,	1999
District I 1625 N. French Dr., Hobbs, NM 88240				WELL A			
District II	OIL CONSERV	30005-61		f I aggs			
811 South First, Artesia, NM 88210 District III	2040 South Pacheco Santa Fe, NM 87505			5. Indicate Type of Lease  STATE FEE  6. State Oil & Gas Lease No.			
1000 Rio Brazos Rd., Aztec, NM 87410							
District IV 2040 South Pacheco, Santa Fe, NM 87505					o. State on & das Ecase 140.		
SUNDRY NOTICES AND REPORTS ON WELLS					Name or	Unit Agreement Na	ime:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					Twin Lakes San Andres Unit		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					kes San A	indres Unit	
1. Type of Well:							
Oil Well Gas Well Other Injection					l No.		
2. Name of Operator	•					108	
Concho Oil & Gas Corp.  3. Address of Operator					name or V		
110 W. Louisiana Ste 410; Midland, Tx 79701				Twin Lal	ces; San A	Andres (Assoc)	
4. Well Location							
	0 1 0 1	1:	and 2310 feet	from the	East	line	
Unit Letter J: 2310 Fe	eet from the South	nne	and	mom uic _	Last		
Section 7	Township 9S	Ran		NMP	M Cha	aves County	energy of ACC
Section 1	10. Elevation (Show w	vhether DF	R, RKB, RT, GR, et	c.)			
Military and the same of the s	3921 GR		CD7 ()	D ( )			de la constante de la constant
11. Check Ap	propriate Box to Inc	dicate Na	iture of Notice,	Report of	Other L	Jaia JODT OF:	
101020111011101					N I KEF	PORT OF: ALTERING CASIN	ıg 🗀
PERFORM REMEDIAL WORK	LUG AND ABANDON X		REWEDIAL WORK				
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OP	NS. 🔲	PLUG AND	
	MUTIDLE		CASING TEST A	ND		ABANDONMENT	
I OLL OIL ALL OF TOTAL	CASING MULTIPLE CASING TEST AND CEMENT JOB				ليا		
			071150				Г
OTHER:			OTHER:		ant datas i	including actimated	date
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
of starting any proposed work). or recompilation.	SEE RULE 1103. FOI	Mumpie	ompictions. Titue	on wondere	aragrari.	F F F F F F F F F F F F F F F F F	
•							
Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:							
<ol> <li>Notify the NMOCD Artesia</li> </ol>	District 24 hours prior	to comme	ncement.				
<ol> <li>Set 100' cmt plug @ 2625-2</li> <li>Circ hole w/ mud.</li> </ol>	1725'. WOC & tag.					ga sa s esa la	
3. Circ hole w/ mud. 4. <b>25</b> Set 100' cmt plug @ 1550-2	2080'.				į, i	1916 P At 16	
5.25 Set 100' cmt plug @ 1500	1500'						
6. 2< sxSet 150' cmt plug @ 7=3-94	10'.						
7. Circ cmt from 217' to surfac	CC.					113.	
8. Cut off wellhead & install P	&A marker.					OFCENVEDSIA	
						JCD AKIN	
						70.e	
I hereby certify that the information	above is true and comp	lete to the	best of my knowle	dge and bel	ief.		
XIII	At	TITLE	Production And	alvst	DATE	1-11-02	
SIGNATURE		111LL:	1 Todaction 71nd	utyst			_
Type or print name Terri Stath	em		Telephone No. 91	5/683-7443	,		
(This space for State use)	000		1 -11	/] -	777	A CONTRACTOR OF THE CONTRACTOR	
(	/ 'V	_TITLE_	Juld	Sed		DATE	
APPPROVED BY	<b>16</b> \	_TTTLE_				DATE	
Conditions of approval, if any:				Ş.			

## **TLSAU #108**





Original Perf Details: P1: 2683.5, 84, 88, ,89, 95, 96, 2704, 05, 06, 12, 13

5000 gals 20% acid

Jun-89 Found csg leak above TOC. Cut csg @ 799'. Ran new csg. Perf @ 810'. Circ cmt to surface.