STATE OF NEW MEXICO MERGY AND MINERALS DEPARTMENT

THUT AND WINCHALD DO	CAH	IIAIC
we. or corits acclives		
DISTRIBUTION	T	
SANTA FE	$I_{\mathcal{L}}$	
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR	17	

OIL CONSERVATION DIVISION

DISTRIBUTION		P. O. BOX		4000		Form C-103 · Revised 10-1-78
SANTA FE		SANTA FE, NEW	MEXICOF [1356]	1982	•	
FILE		·			5a. Indicate Type	
U.S.O.S.			O, Ĉ	. D .	State	Foo X
OFERATOR			ARTEGIA,		5. State Oil & Go	ıs Lease No.
Tor Education			5437 ; r.b. 10 47			
	SUNDRY NOTIC	ES AND REPORTS ON I	WELLS		THITTE	MITTITI
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FOR C-101) FOR SUCH PROPOSALS.)						
	E AVELCATION TO C.			· · · · · · · · · · · · · · · · · · ·	7. Unit Agreemer	nt Name
OIL X WE	S OTHER-					
iame of Operator					8. Farm or Lease	e Name
Stations On	erating Corpora	ation /			O'Brien	וורוו
Address of Operator	stacing corpora	icion /			9. Well No.	
-	2202 Dogga211	Nou Movido 99201			5	
ocation of Well	2203, ROSWELL,	New Mexico 88201		9	10. Field and Pa	ool, or Wildcat
			7.550	(/		s-San Andres
UNIT LETTER G		FEET FROM THE East	LINE AND	FEET FROM	ASSOC.	mmm
3717-						
North	LINE, SECTION	2 TOWNSHIP 9S	RANGE28E	NMPM.		
	mmmm	(6)	DE DE CD		777777777777777777777777777777777777777	444444
		15. Elevation (Show whether D			12. County	
	//////////////////////////////////////	3917.0 GL, 3922.0	J KB		Chaves	_7/////////////////////////////////////
	Check Appropri	ate Box To Indicate Na	ature of Notice, F	leport or Oth	er Data	
тои	ICE OF INTENTIC	_		_	REPORT OF	:
	•	i		•		
STORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTER	RING CASING
MFORARILY ABANDON			COMMENCE DRILLING OF	ия. 💢	PLUG .	AND ABANDONMENT
LE OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEME			
	—		OTHER Perfo	rations an	<u>d Acid Trea</u>	utment X
OTHER						
Describe Proposed or work) SEE RULE 1103		Clearly state all pertinent detai	ils, and give pertinent	dates, including	estimated date of	starting any proposed
WOIR) SEE NOCE TION	,•					
1-19-82		joints 8 5/8" 24.0:				
	129' with 75	sacks Class "C", 29	% CaCl ₂ . Circ	ulate 20 s	acks. WOC	18 hrs.
		1000# for 30 minutes				
	-					
1-25-82	Ran 78 joints	s 4 1/2" 9.5# casing	q. Set in cem	ent at 273	2' with 200)
	sacks self st	tress. WOC 18 hrs.	Pressure up	1000# for	30 minutes	
		ressure decrease.	•			
	- ۱ د در	·				
1-29-82	Perforated at	t 2588, 88.5, 89, 9	4, 94.5, 95, 2	600.5, 260	1, 2601.5,	
		.5, 07.5, 08, 08.5,			•	
		, , , , , , , , , , , , , , , , , , , ,		-		
2-2-82	Ran 79 ioints	s 2 3/8" and 18' sul	b to depth of	2463', set	packer.	
		000 gals of 28% HCL		,		
			-			

2 2 02	Acidized w/8000 gals		HCT.	Pacifica	•	
	Totalisa II, 0000 gail	. 01 100				
		•				
,						
	·				-	•
18. I hereby certify that th	e information above is true and com	nplete to the b	best of my knowledge and belief.			
SIGNED Pat J.	Kompson		Production Coordinator	DATE_	2-4-82	
m	b. William	YITLE	OIL AND GAS IMPRECION	DATE	FEB 8	1982
CONDITIONS OF APPROX	VAL, IF ANY					
			•			