


STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2
SANTA FE, NEW MEXICO 87501



Form C-103
Revised 10-1-73

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Plug to Abandon		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator McClellan Oil Corporation		5. State Oil & Gas Lease No.
3. Address of Operator P.O. Drawer 730, Roswell, NM 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER L, 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 9-S RANGE 26-E NMPM.		8. Farm or Lease Name Finch Fee
		9. Well No. 2
		10. Field and Pool, or Wildcat South Pecos Slope
15. Elevation (Show whether DF, RT, GR, etc.) 3694' G.L.		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and Abandoned as follows:

12/13/83: Circulated hole with salt mud from 1200' to surface. Filled annulus with salt gel.
 Set 30 sacks Class "C" plug at 1250'.
 Set 25 sacks Class "C" plug from 60' to surface.
 Installed dry hole marker. Removed all surface equipment and will clean location and rip road.

Post ID-2
12-23-83
PST

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Paul Fagdale</u> TITLE Operations Manager	DATE 12/14/83
APPROVED BY <u>Paul Moore</u> TITLE Geologist	DATE 1/31/84

CONDITIONS OF APPROVAL, IF ANY: