

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

# NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

MAR 24 1982

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation		8. Farm or Lease Name Fahrlander Fee
3. Address of Operator P.O. Drawer 730, Roswell, N.M.		9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 6S RANGE 27E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4026' GL		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/19/82 Plug and Abandoned well as follows:

Set a 30 sack Class C plug from 5098'-5198'

Set a 30 sack Class C plug from 4648'-4748'

Set a 35 sack Class C plug from 2507'-2607'

Set a 65 sack Class C plug from 1384'-1484'

Waited 2 hours and tagged plug at 1380' with drill pipe ;

Set a 15 sack plug from 60' to surface and installed dry hole marker.

Heavy mud was placed between each plug.

After pits dry, the location will be leveled and cleaned and restored to its original condition.

Set a 35 sack Class C plug from 3912-4012

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Ragsdale

TITLE Operations Manager

DATE 3-22-82

APPROVED BY Larry Brooks

TITLE Geologist

DATE 10/6/83

CONDITIONS OF APPROVAL, IF ANY: