

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-78

MAR 31 1983

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 335
7. Unit Agreement Name
8. Farm or Lease Name Springer TK State
9. Well No. 2
10. Field and Pool, or Wildcat Und. Pecos Slope Abo
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☐ P&A

Name of Operator
Yates Petroleum Corporation

Address of Operator
207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE East LINE, SECTION 23 TOWNSHIP 4S RANGE 24E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

4043.6' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4100'. Plugged well as follows:

Pulled tubing, rods and pump. Set CIBP at 3600'. Cut casing at 3175' and pulled.

Plug #1: Set CIBP at 3600' and capped w/55 sacks Class "C" 2% CaCl₂. Tagged at 3000'.

Plug #2: Set 50 sacks Class "C" 2% CaCl₂ at 1645-1545'.

Plug #3: Set 45 sacks Class "C" 2% CaCl₂ at 1014'. Tagged cement at 800'.

Plug #4: Set 15 sacks Class "C" plug at surface.

Installed dry hole marker. Cleaned location.

Verbal plugging obtained from Mr. Larry Brooks, NMOCD, Artesia, 3-23-83.

Post ID-2
4-8-83
PVA

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry Brooks

TITLE Production Supervisor

DATE 3-31-83

APPROVED BY

Larry Brooks

TITLE

Geologist

DATE

5-2-85

CONDITIONS OF APPROVAL, IF ANY: