## STATE OF NEW MEXICO INERGY AND MINERALS DEPARTMENT

HO. OF COMICS RECEIVES		
DISTRIBUTION		-
SANTA FE	17	
PILE	1	1
U.S.G.S.		
LAND OFFICE		1
OPERATOR	1 j	T

HA, OF COPIES RECEIVES		IL CONSERVA	LION DIMEGENTARIO	9			
DISTRIBUTION		P. O. BOX	< 2088			Form C-103 Revised 10-1-78	
SANTA FE		SANTA FE, NEW	MEXIQQ,87501			KG11264 10-1-14	
PILE	1		MEX198L8759198	2 Sa. 1	ndicute Type o	Leuso	
U.\$.G.\$.	1				State X	Foo	
LAND OFFICE			O. C. D.		ate Oil & Gas		
OPERATOR			ARTESIA, OFFICE	5. 50		Lease No.	
			OFFICE		LG-338		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
OIL GAS WELL	X OTHER-				nit Agreement l		
Conse of Operator			1	8. Farm or Lease Name			
Yates Petroleum Corporation/			E	Eureka UK State			
Address of Operator 207 South 4th St., Artesia, NM 88210				9. W	9. Well No.		
Location of Well				10.	10. Field and Pool, or Wildcat		
UNIT LETTER D 660 FEET FROM THE NORTH LINE AND 660 FEET FROM			W	Wildcat Abo			
UNIT LETTER, OUD FEET FROM THE MODELL LINE AND OUD FEET FROM		_ ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
THE West LINE, SECTION 20 TOWNSHIP 10S MANGE 26E NMPM.							
THE WEST LIN	IE, SECTION ZU	TOWNSHIP TOS	MANGE	NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)			12.	County	444444		
3776.5' GR			C	haves			
. (	Check Appropriate	Box To Indicate N	ature of Notice, Rep	port or Other D	Jata		
NOTICE OF INTENTION TO: SUBSEQUENT							
LRFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK			g CASING	
MPORABILY ABANDON			COMMENCE DRILLING OPHS.	7	PEUG AN	D ABANDONMENT	
LL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT	•		<b>ਿ</b> ਹ	
		r—1	OTHER Product:	ion Casing		X	
OTHER							
			<del></del>	. , ,.			
. Describe Proposed or Comwork) SEE RULE 1103.	pleted Operations (Clea	arly state all pertinent deta	ails, and give pertinent dat	es, including estim	ated date of st	arting uny propos	

TD 4800'. Ran 117 joints of 4-1/2" 10.5# K-55 ST&C casing set at 4800'. 1-regular guide shoe at 4800'. Float collar at 4760'. Cemented w/300 sacks 50/50 Poz "C". Compressive strength of cement - 1275 psi in 12 hours. PD 6:00 AM 6-20-82. Bumped plug to 1000 psi, released pressure and float held okay. Ran 41 joints of 1" and cemented w/400 sacks Halliburton Lite. PD 11:30 AM 6-20-82. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 30 sacks to pit. WOC.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. JUL 1 6 1982 OIL AND GAS INSPECTOR