

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

APR 30 '90

O. C. D.

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

WALLACE OIL & GAS INC. ✓

3. Address of Operator

500 PEEN PLACE, STE. 850, OKLAHOMA CITY, OK 73118

4. Well Location

Unit Letter J : 1980 Feet From The E Line and 1980 Feet From The S Line

Section 8 Township 11-S Range 25-E NMPM CHAVEZ County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3505' GL

7. Lease Name or Unit Agreement Name

PAYTON

8. Well No.

9. Pool name or Wildcat

~~WILDCAT~~ S. Lucas Hope Also

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SET CEMENT PLUG @ 4370' - 3984' 50' ABOVE 4 1/2" SHOE.

2. SET CEMENT PLUG @ 3708' - 3608'.

3. SET CEMENT PLUG @ 3100' APPX. @ 4 1/2" SUB - 50' IN & 50' OUT. TAG.

4. SET CEMENT PLUG @ 1445' - 1345' ~~6 1/2"~~ TAG. 8 5/8" SHOE. * 8 1/8" shoe @ 1232'

5. SET CEMENT PLUG @ 740' - 640'.

6. SET CEMENT PLUG @ 506 - 406' . 13 3/8" SHOE.

7. SET CEMENT PLUG @ SURFACE. 10 SK.

8. INSTALL P & A MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

RAYMOND MALDONADO P & A SUPV., CEMENTER

SIGNATURE Raymond Maldonado TITLE BABER WELL SERVICING CO. DATE 4-26-90

TYPE OR PRINT NAME RAYMOND MALDONADO

TELEPHONE NO. 505-393-5516

(This space for State Use)

APPROVED BY Danell Moore TITLE Dist Seal DATE 5/2/90

CONDITIONS OF APPROVAL, IF ANY:

* Plug #4 has to cover 8 5/8" shoe or an extra plug has to be run.