

STATE OF NEW MEXICO.
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-78

MAY 31 1983

O. C. D.
ARTESIA, OFFICE

3a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Wallace Oil & Gas, Inc. ✓ 3. Address of Operator 50 Penn Place, Suite 850, Okla. City, OK 73118 4. Location of Well UNIT LETTER <u>I</u> <u>1290</u> FEET FROM THE <u>East</u> LINE AND <u>1800</u> FEET FROM THE <u>South</u> LINE, SECTION <u>20</u> TOWNSHIP <u>11S</u> RANGE <u>25E</u> N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) Gr. 3522'	7. Unit Agreement Name 8. Farm or Lease Name Pomona 9. Well No. 1 10. Field and Pool, or wildcat Wildcat-Abo 12. County Chaves
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Report on Plug back</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/22/83 Set Baker Cast Iron bridge plug at 3700'. Spotted with 5 sxs Class C at 3500'. Cut off casing at 3350'. Spot with 50 sxs Class C at 3350' to 3250'. Spot 50 sxs Class C at 1420' to 1320'. Pulled total of 82 joints plus 1 cut off joint. Total of 3350' of casing recovered. Set cast iron bridge plug 8 5/8" at 1245'. Ran Gamma Ray log 1245' to 700'. Good correlation. Waiting on orders.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pamela S. Lanett TITLE Production Sec. DATE 05/24/83
Original
Leslie A. Clements
Supervisor District II
APPROVED BY _____ TITLE _____ DATE AUG 09 1983

CONDITIONS OF APPROVAL, IF ANY: