

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

3a. Indicate Type of Lease	
State ☐	Fee ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.		
OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name TLSAU
Name of Operator PELTO OIL COMPANY		8. Firm or Lease Name
Address of Operator 500 DALLAS, SUITE 1800, HOUSTON, TX 77002		9. Well No. 118
Location of Well UNIT LETTER B, 330 FEET FROM THE North LINE AND 2310 FEET FROM The East LINE, SECTION 18, TOWNSHIP 9S, RANGE 29E, 60PM.		10. Field and Pool, or Wadcut Twin Lakes SA Assoc.
11. Elevation (Show whether DF, RT, GR, etc.) 3974 GR		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
WELL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☒ Converted to water injection well

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-8-88 RUPU (Monument). Pulled & LD rods, pump & tbq. RDPU.
- 3-9-88 RUPU. PU & ran 4 3/4" bit, 5 1/2" csg scraper on 2 3/8" workstring to tag PBTD @ 2794'. Last 30' had a lot of scale buildup. Pulled tbq, scraper & bit. RU Star Tool. Cleaned out last 30' & drilled up 2' more of rathole. PBTD @ 2796'. RD Star Tool. Pulled tbq & bit. PU & ran Guiberson BP & pkr. Set BP @ 2741'. RU Gold Star pump truck & press up csg between BP & surface @ 500#. Held OK. SDON.
- 3-10-88 Latched on BP & lowered to 2788'. RU Goldstar. Spotted 30 gal 20% NEFE acid over area to be perf. RD Goldstar. Pulled & LD tbq, BP & pkr. RU Schlumberger. Perf 8 additional holes in P-1 using 4" csg gun, 1 JSPF @ 2773, 2780, 2781, 2782, 2785, 2786, 2787, & 2788'. RD Schlumberger. PU & ran Halliburton R-4 pkr & 85 jts (2683') 2 3/8" plastic coated tbq. RU Goldstar pump truck & pumped 10 bbls corr inhib wtr down csg-tbg annulus. Set pkr @ 2696'. Loaded csg-tbg annulus w/inhib wtr. Press up csg @ 300#. Ran chart 30 min. RDPU. JOB COMPLETE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Herni Males TITLE Production Administration Mgr DATE April 8, 1988
Original Signed Mike Williams
APPROVED BY Mike Williams TITLE Off & Coor Insp DATE MAY 6 1988
CONDITIONS OF APPROVAL, IF ANY: