

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR

DEPCO, Inc.

3. ADDRESS OF OPERATOR

800 Central, Odessa, Texas 79761

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: A-660 FN & EL, Sec. 20, T-5S, R-25E

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) Spud & S.C.

SUBSEQUENT REPORT OF:

☒

☐

☐

☐

☐

☐

☐

☐

☐

RECEIVED

OCT 5 1982

O. C. D.

ARTESIA OFFICE

5. LEASE

NM 36408

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rosa Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Pecos Slopes ABO

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 20, 5, 25

12. COUNTY OR PARISH

Chaves

13. STATE

New Mex.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3821 KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9-9-82 Drld. 26" hole to 40' & ran 40' of 20" 42# conductor pipe & cmt. w/6 1/2 yds. Redi-mix.

9-13-82 Drld. 14 3/4" hole to 1000'. Ran 31 jts. 42 & 47# 11 3/4" csg. sat @ 999' Cmt. w/375 ex. Howco Lite w/1/4# Flocele, followed w/200 ex. Class "C" w/2X CaCl. circ. 50 ex.

9-14-82 Tested pipe & BOP @ 1000# for 30 min. Tested OK.

9-20-82 Drld. 7 7/8" hole to TD 4230'. Ran logs. Ran 105 jts. 4 1/2" 10.50# J-55 csg. Set @ 4226' w/DV Collar @ 1776'. Cmt. w/300 ex. 50/50 Pozmix "C" w/5# salt. P/ex., .3 of 1X CFR-2 & .3 of 1X Haid 4. Plug down @ 8:30 AM 9-21-82.

9-21-82 Cmt. 2nd stage w/360 ex. 50/50 Pozmix "C" w/5# salt P/ex. Plug down @ 1:00 PM. 9-21-82. TOC 1125.

9-23-82 Ran 1" Pipe to 1125' & cmt. w/360 ex. Howco Lite w/2X Ca Cl. Circ. cmt. to surface.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED L. L. Denney TITLE Chief Clerk DATE 9-28-82

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL IF ANY:

OCT 4 1982

U.S. GEOLOGICAL SURVEY  
ROSWELL NEW MEXICO

See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.