

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR

DEPCO, Inc. ✓

3. ADDRESS OF OPERATOR

800 Central, Odessa, Texas 79761

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

E-660 FN & EL, Sec. 21, T 5s, R 25e
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☒
☒
☐
☐
☐
☐
☐
☐

5. LEASE

NM 36408

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

RECEIVED

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME JAN 18 1983

Rose Federal Com.

9. WELL NO.

11

O. C. D.

ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME

Pecos Slopes Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21, S. 25

12. COUNTY OR PARISH

Chaves

13. STATE

New Mex.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3790 GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-17-82 Drld. out cnt. to 4218' PBTD.

12-20-82 Perf. w/1 - 44" hole @ 3713-16', 20-24', 31-35', 37', 38', 47-49', 3853-58', 60', 62', 63', 66-68', 76-77', 4096', 97', 99', 4100-02', Acidized from 4096-4102', w/1800 gal. 7 1/2% Abo acid w/1000 SCF-N₂ per bbl.

12-21-82 Acidized from 3853-3877' w/2400 gal 7 1/2% Abo acid w/1000 SCF-N₂ per bbl. Acidized from 3713-3749' w/2400 gal 7 1/2% Abo acid w/1000 SCF-N₂ per bbl.

12-24-82 Frac w/73,000 gal Mini-Max. III-30, 104,000# 20/40 sand, 54,000# 10/20 sand, & 347 bbls. CO₂. Preparing to start testing.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Denney R. L. Denney TITLE Chief Prod. Clerk DATE 12-28-82

ACCEPTED FOR RECORD (This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY

JAN 17 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

DEC 30 1982

IMMEDIATE
ROSWELL, NM

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

