Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department RECEIVED OIL CONSERVATION DIVISION

Form C	-103
Revised	1-1-89, 5

I ISTRICT I

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO.			
DISTRICT II Santa Fe, New Mexico \$204-1080	30-005062639			
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE XX			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 O. C. D.	6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name			
1. Type of Well: OBL GAS WELL X WELL OTHER	Mustang			
2. Name of Operator Fred Pool Drilling, Inc.	8. Well No.			
3. Address of Operator	9. Pool name or Wildcat			
P.O.Box 1393, Roswell, N.M .88201	Wildcat- Montoya			
	0 Feet From The <u>East</u> Line			
Section 11 Township 6s Range 27E	NMPM Chaves County			
4056 GR	<u> </u>			
11. Check Appropriate Box to Indicate Nature of Notice, R	eport, or Other Data			
NOTICE OF INTENTION TO: SUB	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT S			
PULL OR ALTER CASING CASING TEST AND CE	CASING TEST AND CEMENT JOB			
OTHER: OTHER:				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.	ding estimated date of starting any proposed			
August 1, 1989: Set CIBP at 4860 ft. via tub TIH with tubing to 4860. Loa 10# mud. Spotted 25 sx plug from 4860 to 454	nded hole with			
August 2, 1989: Ran free-point, casing is free off casing at 2000' layed down casing. Trip to 2550' and spotted 25 sx plug(120') from 25 top of Glorietta formation.) Pulled up to 25 sx plug at 2060' (across stub).	in hole with tubing \mathcal{N}_0 to 2430' (across			
August 3, 1989: Tagged stub plug at 1935'. spotted 40 sx plug accross shoe of surface pi	Pulled up to 1392', ipe. WOC 2hrs. continued page 2			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	and the second second			
SIGNATURE SIGNATURE VICE Pr	resident pare 8-17-89			
TYPE OR PRINT NAME Penta Pool	TELEPHONE NO. 505 623-820			
(This space for State Use)	5/12/98			

CONDITIONS OF APPROVAL, IF ANY:

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico

Form C-103

OIL CONSERVATION PLANES ON P.O. BOX 2088 Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 87504-2088 SEP -1 PA STATE FEE SUNDRY NOTICES AND REPORTS ON WELLS. (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL CONSERVATION FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUGATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL CONSERVATION FOR STATE STATE STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Mustang 8. Well No. 1. Type of Well: OIL CONSERVATION FOR STATE STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Mustang 8. Well No. 1. Type of Well: OIL CONSERVATION FOR STATE STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Mustang 8. Well No. 1. Type of Well: OIL CONSERVATION FOR STATE STATE STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Caster No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Caster No. 7. Lease Name or Unit Agreement Name PLUGAM C-101) FOR SUCH PROPOSALS TO A DIFFERENT STATE FEE 6. State Oil & Gas Caster No. 7. Lease Name or Unit Agreement Name PLEAS TO A STATE FEE 6. State Oil & Gas Caster No. 7. Lease Name or Unit Agreement Nam	to Appropriate District Office	Energy, Minerals and Natural Reso	ources Department	Ke	evised 1-1-07
Santa Fe, New Mexico 87504-2088 Sindicate Type of Lass STATE FED	iner pict i	OIL CONSERVATION	FOTATION		
FO. DISTRICTION SUNDRY NOTICES AND REPORTS ON WELL SUNDRY NOTICES AND REPORTS ON WELL SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR HELD BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: WELL WELL WELL WELL OTHER ONE Pred Pool Drilling, Inc. 3. Address of Operator P. O. Box 1393, Roswell, N.M. 88201 Wildcat—Montoya 4. Well Losation Unit Letter G: 1980 Feet From The North Line and 1980 Feet From The East Socion 11 Township 6S Range 27E NMFM Chaves Company of the Chaves Of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONME Work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	DISTRICT II	P.O. Box 2088 Santa Fe. New Mexico 8	7504-2088		62639
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PETITION FOR PEERNIT RESERVOR. USE "APPLICATION FOR PEERNIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: ORL WELL ONE WELL ONE ONE ONE ONE ONE ONE ONE	P.O. Drawer DD, Artesia, NM 88210			STATE	FEE X
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DELPEN OF THUS BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ONE OBL OR OBL OBL OBL OBL OBL OBL	DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	`	July - 1 (1)	6. State Oil & Gas Lease No.	
OTHER OTHER OTHER OTHER OTHER OTHER OTHER OTHER Name of Operator Name of Operator P.O. Box 1393, Roswell, N.M. 88201 North Line and 1980 Feet From The East North Line and 1980 Feet From The East North Chaves Completed Operator 10. Elevation (Show whether DF, RKB, RT, GR, etc.) A056' NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULIC OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	(DO NOT USE THIS FORM FOR PRODIFFERENT RESE	OPOSALS TO DRILL OR TO DEEPEN C RVOIR. USE "APPLICATION FOR PERI	AH PLUG BACK TO A	7. Lease Name or Unit Agreemen	nt Name
2. Name of Operator 3. Address of Operator P.O. Box 1393, Roswell, N.M. 88201 4. Well Location Unit Letter G 1980 Feet From The North Line and 1980 Feet From The East Section 11 Township 6S Range 27E NMPM Chaves Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 8. Well No. 1 9. Pool name or Wildcat W	1. Type of Well: OIL GAS	1		Muctana	
3. Address of Operator Fred Pool Drilling, Inc. P.O. Box 1393, Roswell, N.M. 88201 Wildcat— Montoya Wildcat— Montoya Wildcat— Montoya 1980 Feet From The Line and 1980 Township 6S Range 27E NMFM Chaves Compared to Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME CASING TEST AND CEMENT JOB PAGE OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting amy proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.		OTHER			
P.O.Box 1393, Roswell, N.M. 88201 Wildcat= Montoya Wildcate Montoya Wildcate Montoya Wildcate Mont		end Prilling Inc			
4. Well Location Unit Letter G: 1980 Feet From The North Line and 1980 Feet From The East Section 11 Township 6S Range 27E NMPM Chaves Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	1. Allies of Operator				
Unit Letter G: 1980 Feet From The NOTTH Line and 1980 Feet From The EdSt Section 11 Township 6S Range 27E NMPM Chaves Co 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4056' 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	P.O.Box 1393,	Roswell, N.M. 88201		Wildcat- Monto	ya
Section 11 Township 6S Range 27E NMPM Chaves Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) See RULE 1103. 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4. Well Location	37 - m L la	1080	n w. Eas	st Line
Section 11 Township OS Range 2.13 INDIAN 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONME PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	Unit Letter G : 19	80 Feet From The NOTTH	Line and 1900	Feet From The	Line
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4056' 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING DATE: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	11	Township 6S Rat	ee 27E	NMPM Chaves	County
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	Section 11	10. Elevation (Show whether L	OF, RKB, RT, GR, etc.)	V/////	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	11. Check	Appropriate Box to Indicate N	lature of Notice, R	leport, or Other Data	OF 1
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	NOTICE OF IN	ITENTION TO:	SUE	3SEQUENT REPORT	OF:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME PULL OR ALTER CASING CASING TEST AND CEMENT JOB Page OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.		r—1	REMEDIAL WORK	ALTERING	CASING
PULL OR ALTER CASING CASING TEST AND CEMENT JOB Page OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	<u></u>			G OPNS. PLUG AND	ABANDONMENT 🔀
OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.		,		L	page 2
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	PULL OR ALTER CASING	CASING TEST AND C			
August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.					
August 3, 1989: Tagged plug at 1295'. Pulled up and spotted 25sx plug at 350' Pulled up and spotted 15x plug at surface.	12. Describe Proposed or Completed Operatory) SEE RULE 1103.	erations (Clearly state all pertinent details, an	d give pertinent dates, incl	uding estimated date of starting any	proposed
Dry hole marker set. Plug and Abandon completed.	August 3, 19	25sx plug at 35 Pulled up and s	0' potted 15x p	olug at surface.	
		Dry hole marker	set. Plug	and Abandon com	pietea.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	I hereby certify that the information above is	true and complete to the best of my knowledge and	i belief.		0 47000
SIGNATURE Senta Soul TITLE Vice President DATE 8-170	SIGNATURE Senta	<u>∫βολ</u> π	me <u>Vice Pre</u>	esident DATE -	8-17089
TYPE OR PRINT NAME Penta Pool TELEPHONE NO.505-62	TYPE OR PRINT NAME	Penta Pool		TELEPH	IONE NO.5 <u>05-623-</u> 820
(This space for State Use) The State Use) DATE 5/12/58	(This space for State Use)		Lie Dan	DATE -	5/12/98