	~			
Submit 3 Copies to Appropriate District Office	State of New Energy, Minerals and Natural		nta Fe ie BLM Form C-103 Revised 1-1-89 B of M	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240			Operator WELL API NO. 30-005-62659	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. LG-4928		
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT CEIVED (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well:  OIL  WELL  GAS  WELL  X	отнек	JUN 23 '80	Dragonfly State Unit	
2. Name of Operator YATES PETROLEUM CORPOR	ATION		8. Well No.	
3. Address of Operator 105 South 4th St., Art	esia, NM 88210	ARTESIA, OFFICE	9. Pool name or Wildcat Undes. Foor Ranch PrePermian	
4. Well Location  Unit Letter 0 : 660 Feet From The South Line and 1650 Feet From The East Line  Section 31 Township 9S Range 27E NMPM Chaves County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)				
3916' GR				
11. Check NOTICE OF IN	Appropriate Box to IndicaTENTION TO:		Report, or Other Data  SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	IG OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	r		CASING TEST AND CEMENT JOB	
OTHER: Set production csg, perforate, treat X  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed				
<ol> <li>Describe Proposed or Completed Oper work) SEE RULE 1103.</li> </ol>	ations (Clearly state all pertinent detail	ils, and give pertinent dates, incl	uding estimated date of starting any proposed	
6695'. Float Shoe set stages as follows: S CFR-3 (yield 1.41, wei	6695', float collar tage 1 - 425 sx 65/3 ght 14.2). PD 9:45 1 6 hours. Stage 2 eight 12.7). Tailed PM 6-9-89. Bumped 5'. 0 holes-4 SPF) .45"	set 6653'. DV t 5 PP Poz "C" + 5# AM 6-9-89. Opene - 300 sx Hallibur in w/200 sx Clas plug to 1000 psi, holes.	" 15.5# J-55 ST&C casing set ool set 2595'. Cemented in two /sx Salt + .4% Halad-4 + .3% d DV tool with 1200 psi. ton Lite + 6#/sx Salt + 1/4#/sx s "C" + 5#/sx Salt (yield 1.32, float and casing held okay.	

I hereby certify that the information above is took and complete to the best of my knowledge and belief.

SIGNATURE TYPE OF PRINT NAME

Juanita Goodlett

THE Production Supervisor

DATE 6-21-89

TELEPHONE NO. 505/748-1471

(This space for State Use)

DATE AUG 2 9 1989

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: