Submit 3 Copies	State of New Mo			Form C-103
to Appropriate District Office	Energy, Minerals and Natural R	esources Department : CEIVED		Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	QIL CONSERVATIO	N DIVISION	WELL API NO.	
	P.O. DOX 2000		30-005-62660	
DISTRICT II Santa Fe, New Mexic P.O. Drawer DD, Artesia, NM 88210.		M 70 3 20 20	5 Indicate Type of Lease	TEX FEE
DISTRICT III	JAN 20 <b>'89</b>	O. C. D.	6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 8741		RTESIA, OFFICE	K2114	
SUNDRY NO	TICES AND REPORTS ON WE			
( DO NOT USE THIS FORM FOR F DIFFERENT RES	PROPOSÀLS TO BRILL OR TO DEEPEN SERVOIR, USE "APPLICATION FOR PE	OR PLUG BACK TO A RMIT"	7. Lease Name or Unit Agree	ement Name
1. Type of Well:	A C-101) FOR SUCH PROPOSALS.)	RECEIVED	Plains State	"16"
08 0A5 ,	X) ones			
well Well {  2. Name of Operator	a j omex	1411 7 700	8. Well No.	
	illing, Inc. 🗸	JAN 17'89	#1	
3. Address of Operator		- C C	9. Pool name or Wildcat	
	3, Roswell, NM 8820	2 O. C. D.	Wildcat - P	re Permian
4. Well Location  Unit Letter $\frac{B}{}$ : $\frac{1}{}$	250 Feet From The North	_	O Feet From The	East Line
, ,	110	29 5		Chaves County
Section 16	Township 115 Ri	mge .	NMPM Y////	
	3695 GR	22 / 1222 / 122 / 222 /	<i>\\\\\\</i>	
11. Chec	k Appropriate Box to Indicate	Nature of Notice, R	eport, or Other Data	
	NTENTION TO:		SEQUENT REPOR	T OF:
NO HOL OF				-
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERIN	G CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			OPNS. PLUG AN	ID ABANDONMENT
PULL OR ALTER CASING CASING TEST AND		CASING TEST AND CE	EMENT JOB K	· ·
OTHER:		OTHER:	<u>,, , , , , , , , , , , , , , , , , , ,</u>	
14 5 7 5 5	perations (Clearly state all pertinent details, a	nd ains mertinent dates inclu	dine estimated date of starting as	ny proposed
work) SEE RULE 1103.	erations (Clearly state all pertinent actaus, at	na give perimeni dales, incid	aing estimated date of sections of	ily proposed
·				
T.D. 4:00 p	.m. 1/3/89.		*	1
Set 8 joints	at 308.4' with 13 3	/8" 48# ST&C	Casing.	
Coment at 30	8' with 300 sx premi	um plus, 2% (	Calcium Cloride	
at 3:30 a.m.	1/4/89. Circulated 50	sx to the pit.		
ac 3.35 a.m.	<b></b>	-		
Waiting on Cem	ent and Pressure Test 18	houre Tost to	600# or bottor fo	)r
30 minutes.	int and flessure lest to	nours. Test ato	OOO# OI DEELEL IC	) <b>.</b>
30 mriidee3.		e grande and a second		
I hereby certify that the information above is	grue and complete to the best of my knowledge and	belief.	, ; ,	•
1) duch	Xx/i de		retaryDATE	1/4/89
SKINATURE ALLECTION	The state of the s			
TYPE OR PRINT NAME			jelen	HONE NO.
en i con en				and the second
(This space for State Use)	Original Signed By	e e e e e e e e e e e e e e e e e e e		JAN 2 4 1989
A PYTROUGHD B V	Mika Williams	ue	DATE	Oma 6 = 1909

CONDITIONS OF APPROVAL, IF ANY: