

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

clsf
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62665
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 5246
7. Lease Name or Unit Agreement Name Pathfinder AFT State
8. Well No. 5
9. Pool name or Wildcat Diablo San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) RECEIVED	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	MAR 03 '89
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	ARTESIA OFFICE
4. Well Location Unit Letter <u>0</u> : <u>330</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>21</u> Township <u>10S</u> Range <u>27E</u> NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3838' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 12 1/4" hole with Frank's Rat Hole 10:00 AM 1-31-89. Notified NMOCD, Artesia, NM. Started drilling 1:30 PM 2-12-89 with cable tool. Ran 13 joints 8-5/8" 24# J-55 ST&C casing set 541'. Regular guide shoe set 541', insert float set 498'. Cemented w/200 sx Halliburton Lite with 1/4#/sx Flocele, 5#/sx Gilsonite + 3% CaCl2 (yield 1.84, weight 12.7). Tailed in w/150 sx Class C + 2% CaCl2 (yield 1.32, weight 14.8). PD 12:15 PM 2-25-89. Bumped plug to 600 psi, released pressure and float held okay. Circulated 25 sacks to surface. WOC. Drilled out 9:00 AM 3-1-89. WOC 92 hours and 45 mins. Cut off and weld on flow nipple. Reduced hole to 8". Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-2-89
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

Original Signed By
Mike Williams

MAR 6 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: