

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

458
Form C-103
Revised March 25, 1999
WELL API NO.
30-005-62722
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
LG-8004
7. Lease Name or Unit Agreement Name:
State 25 Com

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 S. 4th Street Artesia, NM 88210

4. Well Location
Unit Letter **N** : **660** feet from the **South** line and **1980** feet from the **West** line
Section **25** Township **10S** Range **26E** NMPM **Chaves** County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3697' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Attempt Recompletion - perforate, acidize <input checked="" type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 4/10/01 - Set blanking plug in packer at 5963'.

4/11/01 - Perforate Wolfcamp 5276-5282', 13 holes and 5368-5382', 29 holes, .42".

4/12/01 - Acidize perms 5368-5382' with 1400 gals 15% IC HCL. Acidize perms 5276-5282' with 600 gals 15% IC HCL.

4/19/01 - Acidize perms 5276-5282' with 1500 gals 15% IC HCL.

4/23/01 - Perf Cisco 5752-5762' with 40 holes, .41".

4/24/01 - Acidize with 1000 gals 15% IC HCL. Acts like communicated with lower Wolfcamp perms.

4/30/01 - Set retainer at 5218'. Cement squeeze Wolfcamp perms 5276-5382' with 200 sxs C with .2% D65. Squeeze off at 2900#. WOC.

5/2-5/3/01 - TIH with bit. Tag retainer at 5202'. Drill out retainer and cement to 5345'. Test perms 5276-82' to 550#, held OK. Continued drilling cement to 5385' and fell out. Test perms 5368-5382' to 550#, held OK.

5/8/01 - Acidize Cisco perms 5752-5762' with 500 gals 15% IC HCL.

5/9/01 - Acidize Cisco perms 5752-5762' with 1000 gals 15% IC HCL. No shows.

5/16/01 - Pull blanking plug from packer at 5963'.

5/17/01 - Rig down. Turn well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Susan Herpin* TITLE Engineering Technician DATE January 14, 2002

Type or print name Susan Herpin Telephone No. 505-748-1471

(This space for State use)
ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 28 2002
Conditions of approval, if any: