

dsf
dp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1100 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504

NOV 21 '90

WELL API NO. 30-005-62734
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Mesquite Tank
8. Well No. 1
9. Pool name or Wildcat W C
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3729' Gr

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Fred Pool Drilling, Inc.
3. Address of Operator P.O. box 1393, Roswell, N.M. 88201
4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 29 Township 11S Range 28E NMMP Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-90 Set Cast Iron Bridge plug at 5950 feet. Spotted 35 sx Prem Plus Neet on top of plug.

10-23-90 Ran free point, pipe free at 5140 ft. Cut off at 5108 ft. Ran tubing in hole. Spotted 60 sx cement. Tubing at 5158 ft.; tagged top of plug at 4920 ft. Spotted 35 sx cement, tubing at 2851'. Top of plug at 2715 ft. Bottom of 8 " casing at 2384 ft. Set tubing at 2428 ft. spotted 35 sx, agged top at 2392 ft. Set tubing at 2391 ft. spotted 25 sx cement, tagged plug at 2318 ft. Intend to perforate and acidize to test San Andres formation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Penta Pool TITLE Vice Pres. DATE 11-16-90
TYPE OR PRINT NAME Penta Pool TELEPHONE NO. 505 623-8202

(This space for State Use)

ORIGINAL SIGNED BY

APPROVED BY MIKE WILLIAMS TITLE SUPERVISOR, DISTRICT II DATE NOV 30 1990

CONTINUATION OF APPROVAL, IF ANY: