State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexic

co	875	04	.208	38
co R	EC	ĒΝ	EC	

WELL API NO.	
30 005 62734	
5. Indicate Type of Lease	[7]

(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***		STATE FEE (22)
DISTRICT III 11701 Rio Brazos Rd., Aziec, NM 87410	MA	k 0 8 1993	6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERY	CES AND REPORTS ON WELPOSALS TO DRILL OR TO DEEPEN COIR. USE "APPLICATION FOR PEI 101) FOR SUCH PROPOSALS.)	BLUCERIOR IO A	7. Lease Name or Unit Agreement Name Mesquite Tank
I. Type of Well: OIL GAS WELL X WELL	oneA	er et en	1.00-1
7 Name of Operator Fred Pool Dril	ling, Inc.		8. Well No.
3. Address of Operator P.O.box 1393,	Roswell, N.M. 8820	2	9. Pool name or Wildcat WC
4. Well Location Unit Letter M : 66	O Feet From The South	Line and660	Feet From The West Line
Section 29 11. Check A NOTICE OF INT	10. Elevation (5how whether GR 3729 Appropriate Box to Indicate	ft. Nature of Notice, F	Report, or Other Data BSE:QUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON L	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C	· - 1
OTHER:		OTHER:	
work) SEE RULE 1103. March 2, Set Cast at 2161 f	1993 Iron bridge plug w t. t plugs at:2139. ¹³	ith Schlumbe 'with 10 sa	cks prem. neat cement
-			prem.neat cement.

1069.26' with 30 sx. prem.neat cement.

with 30 sx prem. neat cement with 10 sx prem. neat cement 30'

Plan to set dry hole marker, clean location and notify OCD.

I hereby certify this the information above is true and complete to the best of my knowledge and belief. SIGNATURE President DATE 3-3-1)3
TYPE OR PRINT NAME Fred ROOL, Jr. 505 623-8202 TELEPHONE NO.	

OIL AND SAS INSPECTOR